

**REPAIR ESTIMATE**DATE: **27-Sep-21**INSURANCE: **AIG ASIA** *CP/P*MODEL: **Hyundai Ioniq**MVA: **LIM T S**VEHICLE NO.: **SHA9144J - CityCab**

| PART NO. | DESCRIPTION                                      | QTY | UNIT PRICE | AMOUNT            |
|----------|--|-----|------------|-------------------|
|          | Rear Bumper <i>X Repair</i>                      | 1   |            | \$459.40          |
|          | Rear Bumper Cover Clips <i>- abc</i>             | 10  | \$2.20     | \$22.00           |
|          | Rear Bumper Side Bracket LH <i>?</i>             | 1   |            | \$55.80           |
|          | Rear Fender LH <i>X Repair</i>                   | 1   |            | \$1,768.30        |
|          | <b>SUB TOTAL</b>                                 |     |            | \$2,305.50        |
|          | <b>LESS 20%</b>                                  |     |            | \$461.10          |
|          | <b>DISCOUNTED TOTAL</b>                          |     |            | <b>\$1,844.40</b> |
|          | <b> </b>   |     |            |                   |
|          | Rear Fender Advertisement RH / LH <i>- abc</i>   | 2   | \$100.00   | \$200.00          |
|          | Rear Bumper Mat <i>X</i>                         | 1   |            | \$50.00           |
|          | Rear Fender (Petrol Only) LH <i>X</i> <i>3mm</i> | 1   |            | \$40.00           |
|          | <b>S/NETT TOTAL</b>                              |     |            | <b>\$290.00</b>   |
|          | <b>SPARE PARTS TOTAL</b>                         |     |            | <b>\$2,134.40</b> |
|          | <b>Labour Charge</b> <i>450</i>                  |     |            |                   |
|          | Panel Beating                                    |     |            | \$800.00          |
|          | Spray Painting Charge                            |     |            | \$600.00          |
|          | Remove/Refix Reverse Sensor                      |     |            | \$120.00          |
|          | <b>TOTAL LABOUR</b>                              |     |            | <b>\$1,520.00</b> |
|          | <b>ESTIMATE TOTAL</b>                            |     |            | <b>\$3,654.40</b> |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

*3 Days.**P/P**before paint photos.**Gino Qiang**CP: 30 pm**27/9/21**350  
500  
400*