

Steve (LKK)
25/10/21, 11:00a

W.L PL
P/P
L, RL by
4 d/s

SERVICE ESTIMATE

- C00001

SL: SERVICE SALES - PC

Mr W Murray Christopher William
55r Jalan Lim Tai See Estrivillas

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 27/09/2021

WIP No. . : 47754

Veh.In/Out:

*Tel.No. . : Mobile: 82625851

Reg.No. . : SMU8370P

Reg.date . : 31/08/2020

Mileage . : 0

Chassis No: SALCA2AX2LH870798

Singapore 266239

Closed by . . . : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Murray Christophe

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
302	TO REPLACE REAR RH DOOR,	0	1000	3000.00	0		3,000.00	S
	REPAIR FRT RH DOOR, ETC							
800	TO SPRAYPAINT ON	0		2700.00	0		2,700.00	S
	FRT RH DOOR, REAR RH DOOR, ETC							
802	TO REMOVE, REFIT & TRANSFER	0		500.00	0	X	500.00	S
	REAR RH DOOR PARTS							
0031	TO REPLACE REAR RH TYRE	0		850.00	0	X	850.00	S
0031	TO REPLACE REAR RH RIM	0		50.00	0	X	50.00	S
419	WHEEL ALIGNMENT	0		280.00	0	X	280.00	S
280	TO CHECK WIRING INCLUDE	0		621.00	0	X	621.00	S
	RESETTING OF ALL ELECTRICAL							
	MODULES							
NOTES	NOTES	0		0.00	0			S
	DOOR PANEL REAR RH D	1.0	EA	2670.30			2,670.30	S
	SEAL - DOOR FRONT AN	1.0	EA	145.20			145.20	S
	SEAL - DOOR FRONT AN	1.0	EA	254.40			254.40	S
	MOULDING - DOOR OUTS	1.0	EA	283.30			283.30	S

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4700 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

- C00001 SL: SERVICE SALES - PC

Mr W Murray Christopher William
55r Jalan Lim Tai See Estrivillas

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 27/09/2021

WIP No. . : 47754

Veh.In/Out:

*Tel.No. . : Mobile: 82625851

Reg.No. . : SMU8370P

Reg.date. : 31/08/2020

Mileage . : 0

Chassis No: SALCA2AX2LH870798

Singapore 266239

Closed by : Paul Ong Qing Yong

Svc Consultant :

Remarks : Mr Murray Christophe

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	MOULDING - REAR WHEEL ^X	1.0 EA	197.70			197.70	S
	WHEEL - ALLOY ¹⁰⁷	1.0 EA	1460.10			1,460.10	S
	SOUND DEADENING PAD ^X	1.0 EA	578.00			578.00	S
	BUMPER NUT XF ^X	15.0 EA	4.70			70.50	S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour	Total	8,001.00
Parts	Total	5,659.50
Package	Total	0.00

Gross Total. 13,660.50

Net..... 13,660.50

GST @ 7.0% 956.24

Total..... 14,616.75

Paid..... 0.00

Please Pay.. 14,616.75

GST: S=StdRated; O=OutOfScope; Z=ZeroRated