## **SMR 912U**

1		SUPP (PARTS)		<b>LABOUR</b>		S/N				<u>PARTS</u>
,	\$108.68		\$280.00		\$0.00		\$0.00	\$0.00	\$2,382.62	
.]	\$74.51		\$480.00		\$0.00		\$0.00	\$0.00	\$102.32	
	\$300.10		\$1,680.00		\$0.00		\$0.00	\$0.00	\$97.37	
j	\$0.00		\$1,600.00		\$0.00		\$0.00	\$0.00	\$28.44	
<u> </u>	\$0.00		\$840.00		\$0.00		\$0.00	\$0.00	\$26.15	
<u>.</u>	\$0.00		\$420.00		\$0.00		\$0.00	\$0.00	\$20.88	
<u> </u>	\$0.00		\$150.00		\$0.00		\$0.00	\$0.00	\$30.50	
<u> </u>	\$483.29		\$80.00		\$0.00		\$0.00	\$0.00	\$5.00	
<u> </u>	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$266.78	
<u>,</u> ]	0%		\$0.00		\$0.00		\$0.00	\$0.00	\$279.12	
<u>į</u>	<u>\$0.00</u>		\$0.00		\$0.00		\$0.00	\$0.00	\$27.09	
]		SUPP (SN)	\$0.00		\$0.00		\$0.00	\$0.00	\$228.77	
<u> </u>	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$263.29	
<u> </u>	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$104.26	
<u> </u>	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$1,438.75	
<u> </u>	\$0.00		\$0.00		\$0.00		\$0.00	\$0.00	\$332.69	
<u>-</u>	<u>\$0.00</u>		<u>\$5,530.00</u>		\$0.00		\$0.00	\$0.00	\$4.72	
]							\$0.00	\$0.00	\$0.00	
]		SUPP(LABOUR)					\$0.00	\$0.00	\$0.00	
Ī	\$0.00			TOTAL		1	\$0.00	\$0.00	\$0.00	
	\$0.00		\$5,638.75				\$0.00	\$0.00	\$0.00	
	\$0.00		\$0.00				\$0.00	\$0.00	\$0.00	
<u>[</u>	<u>\$0.00</u>		\$5,530.00				\$0.00	\$0.00	\$0.00	
<u>-</u>	<u>\$483.29</u>	TOTAL SUPP	\$483.29	SUPP		1	\$0.00	\$0.00	\$0.00	
)	VOLKSWAGEN TOURAN (1395cc)	MAKE / MODEL	\$11,652.04	P/P			\$0.00	\$0.00	\$0.00	
	\$110,000.00	MARKET VALUE	\$0.00			1	\$0.00	\$0.00	\$0.00	
	\$50,149.00	LTA REBATE	0%			1	\$0.00	\$0.00	\$0.00	
	\$59,851.00	NETT VALUE	\$0.00			1	\$5,638.75	\$0.00	\$0.00	
44%	\$9,291.58	RED	\$0.00	L/S				\$0.00	\$0.00	
	\$20,943.62	TOTAL TP EST			•		\$0.00	\$0.00	\$0.00	
	<u>5</u>	REPAIR DAYS				]	0%	\$0.00	\$0.00	_

\$0.00 <b>\$0.00</b>
----------------------