

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMU4731H (Insd veh)	Model:	MERCEDES-BENZ SPRINTER
	YP4059A (TP veh)		516CDI 2.1 D 3665 HIGH ROOF
Date of Accident:	03/08/2021		A/T ABS (A)

Global Sum Settlement	:	[ ] Yes	[ X ] No	
Repair Estimate	:	\$		<b>2,077.57</b>
Final Repair Cost	:	\$		1,784.45
Loss of Use	:	\$		300.00
				3.00 days at \$100.00 per day
Rental (if any)	:	\$		0.00
				days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		2,086.45

Is Third Party Workshop GIA Registered?				[ ] YES	[ X ] NO	(Kindly indicate below)
A) For <b>Non GIA Registered Workshop:</b>				Agreed Liability _____ 100 _____ (%)		
B) For <b>GIA Registered Workshop:</b>				BOLA Applicable: Yes/ No    BOLA Scenario No: _____		
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.						
Remarks _____						

Payment Instruction: Payee's Breakdown			
1)	Woon Meng Motor Pte Ltd	:	\$ 2,086.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

10 Feb  
2022

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))