SHB 7602L

| | | SUPP (PARTS) | | LABOUR | | S/N | | | | <u>PARTS</u> |
|---------------|-----------------------|--------------|-----------------|--------|----------|-------------------|------------|--------|----------|--------------|
| 0.00 | \$0.00 | | \$200.00 | | \$200.00 | | \$0.00 | \$0.00 | \$442.60 | |
| 0.00 | \$0.00 | | \$400.00 | | \$30.00 | | \$0.00 | \$0.00 | \$576.30 | |
| 0.00 | \$0.00 | | \$0.00 | | \$100.00 | | \$0.00 | \$0.00 | \$15.40 | |
| 0.00 | \$0.00 | | \$0.00 | | \$100.00 | | \$0.00 | \$0.00 | \$332.70 | |
| 0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| 0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| 0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| 0% | | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| <u> </u> | <u>\$0.00</u> | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | | SUPP (SN) | | | \$0.00 | $\overline{}$ | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$0.00 | | \$0.00 | \longrightarrow | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| <u> 30.00</u> | <u>\$0.00</u> | | <u>\$600.00</u> | | \$430.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | | | | | | | \$0.00 | \$0.00 | \$0.00 | |
| | | SUPP(LABOUR) | | | 1 | | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | | TOTAL | | 4 | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$1,025.25 | | | | \$0.00 | \$0.00 | \$0.00 | |
| | \$0.00 | | \$430.00 | | | | \$0.00 | \$0.00 | \$0.00 | |
| | <u>\$0.00</u> | | \$600.00 | | | | \$0.00 | \$0.00 | \$0.00 | |
| <u> </u> | <u>\$0.00</u> | TOTAL SUPP | \$0.00 | SUPP | | | \$0.00 | \$0.00 | \$0.00 | |
| 798cc) | TOYOTA PRIUS (1798cc) | MAKE / MODEL | \$2,055.25 | P/P | | | \$0.00 | \$0.00 | \$0.00 | |
| 0.00 | \$0.00 | MARKET VALUE | \$0.00 | | | | \$0.00 | \$0.00 | \$0.00 | |
| 0.00 | \$0.00 | LTA REBATE | 0% | | | 1 | \$0.00 | \$0.00 | \$0.00 | |
| 0.00 | \$0.00 | NETT VALUE | \$0.00 | | | | \$1,367.00 | \$0.00 | \$0.00 | |
| 10.93 79% | \$7,910.93 | RED | \$0.00 | L/S | | | | \$0.00 | \$0.00 | |
| 66.18 | \$9,966.18 | TOTAL TP EST | | | • | | \$1,367.00 | \$0.00 | \$0.00 | |
| <u>2</u> | <u>2</u> | REPAIR DAYS | | | | | 75% | \$0.00 | \$0.00 | |

| \$0.00 \$1,025.25 REMARKS |
|----------------------------------|
|----------------------------------|