

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7602L**AAD2109-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHB7602L

JTDKB3FU503081963

TOYOTA

PRIUS

15/09/2021

A16-

27/06/2019

PART	
1	COVER, REAR BUMPER
1	GUARD, REAR BUMPER, CENTER
1	COVER, REAR BUMPER, LOWER <i>low cover</i>
1	FILLER, REAR BUMPER EXTENSION, LH RH
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	RETAINER, REAR BUMPER SIDE, LH RH
1	COVER, FLOOR UNDER, NO.1 (LH) RH
1	COVER, REAR FLOOR (CTR)
1	LENS AND BODY, REAR LAMP, LH RH
1	LENS & BODY, REAR COMBINATION LAMP, LH RH
1	COVER, DECK TRIM, REAR
1	PANEL SUB-ASSY, BODY LOWER BACK
1	PANEL SUB-ASSY, BACK DOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	STAY ASSY, BACK DOOR, LH
1	STAY ASSY, BACK DOOR, RH
1	HINGE ASSY, BACK DOOR, LH
1	HINGE ASSY, BACK DOOR, RH

LIST	
\$	442.60 <i>del</i>
\$	576.30 <i>del</i>
\$	15.40 <i>del</i>
\$	123.70 <i>X</i> <i>un</i>
\$	332.70 <i>bt</i>
\$	116.50 <i>X</i> <i>un</i>
\$	175.10 <i>X</i> <i>RH</i>
\$	229.90 <i>X</i>
\$	502.00 <i>X</i>
\$	443.30 <i>X</i>
\$	126.70 <i>X</i>
\$	650.30 <i>X</i>
\$	1,147.80 <i>X</i>
\$	925.60 <i>RH</i>
\$	242.50 <i>X</i>
\$	242.50 <i>X</i>
\$	61.00 <i>X</i>
\$	61.00 <i>X</i>
TOTAL \$ 6,414.90	
25% \$ 1,603.73	
\$ 4,811.18	

1367
1025.25

Special Nett

1	PARKING AID	\$	700.00 <i>200 un</i>
1	REAR FLOOR COVER CLIP	\$	60.00 <i>X</i> <i>un</i>
1	REAR LOWER BUMPER CLIP	\$	65.00 <i>X</i> <i>un</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2109-

SHB7602L

1 REAR BUMPER CLIP	\$	60.00	3 due
1 BOOT STICKER TRANSCAB	\$	100.00	nr
1 BOOT STICKER TEL.NO	\$	100.00	nr
2 WINDSCREEN SEALANT	\$	150.00	X7
1 WINDSCREEN MOULDING	\$	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
TOTAL	\$	1,565.00	430

TOTAL PARTS \$ 6,376.18**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X nr

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 200

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 400

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 X nr

To Check Electrical Lighting Concerned.

\$ 170.00 8 X nr

TOTAL \$ 3,590.00 600**Over All Total \$ 9,966.18****(PART-BY-PART) Repair Days****20 days**

Tanphie 97495749
WP 17/1/21 @ 1150
P/P Resurvey before paint
2 days
Tanphie @ lkhants.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Co.

1025.25

430

600

\$ 2055.25

2 days

Acknowledged by Repairer

Signature:

Date: