



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: CHAN KIAN CHUAN			Ref: CS3/ASM21010052/Gqce2 Date: 30/09/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 6516Z	Veh. Inspected	SKP 8847G
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03IVF	Excess (\$)	0.00
	Assign From	CHAN KIAN CHUAN	Assign Date	28/09/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALLION 1.5	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2008
	Chassis No.	NZT2603023970	Colour	SILVER
	Odometer	320221 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DUNLOP	6 mm
	L/H Front Tyre	195/65 R15	DUNLOP	6 mm
	R/H Rear Tyre	195/65 R15	DUNLOP	6 mm
	L/H Rear Tyre	195/65 R15	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	26/09/2021	Inspect Date / Time	28/09/2021 (05:00 PM)
	Survey held at	DERRICK MOTOR WORKS BLK 9002 #01-72 TAMPINES ST 93 SINGAPORE 528836		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM21010052/Gqce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.