

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref: CS3/III21009316/Gqf3-1	
64 CECIL STREET		Date: 28/09/2021	
#05-02 IOB BUILDING SINGAPORE 049711		Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLJ 5273B	Veh. Inspected	FBR 5356Y
Policy No.	D21MFL0000447	Coverage (\$)	0.00
Claim No.	MFL2021D0003691	Excess (\$)	0.00
Assign From	CARINE KEK PHER SER	Assign Date	28/09/2021
2. Vehicle Particulars & Condition			
Make & Model	c.c 0		
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	Colour		
Odometer	-	Steering	
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/08/2021	Inspection Date	28/08/2021 06/09/2021
Survey held at	YEW HENG GROUP PTE. LTD. 411 CHANGI ROAD SINGAPORE 419860		
	Repairer: A L Motorwerkz		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			