

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188

**TOYOTA****ESTIMATE**

Account Details			Account No. S1000006 / ICIII1		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			Document No. 0		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967			
			Document Date 27/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-GV8627R ACC DATE:27/09/2021 TOW IN:27/09/2021 DATE-IN:27/09/2021 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:						30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR						180.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST						180.00
4	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET , GARNISH AND TRIMMING TO ASSIST REPAIR						360.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL						120.00
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS						462.00
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM						350.00
8	B	BP-LAB2 REMOVE & INSTALL REAR REVERSE CAMERA						180.00
9	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE						360.00
10	S	BP-SUBLET TO RESET ECU AND REPROGRAMME						180.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept	S1000006 / ICIII1	Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967
	Document No. 0	
	Document Date 27/09/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEKB3GH50J002140	8ARZ122346	60	Sam San Joi	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				4320.00
12	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				3540.00
13	1	T52159-48933 COVER, RR BUMPER	1.00	904.00		904.00
14	2	T52156-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70
15	3	T52155-48050 SUPPORT, RR BUMPER	1.00	82.70		82.70
16	4	T52169-48100 COVER, RR BUMPER,	1.00	466.00		466.00
17	5	S52161-0K040 CLIPS	10.00	4.10		41.00
18	6	T52163-48050 PLATE, RR BUMPER, RH	1.00	98.20		98.20
19	7	T52615-48230 ABSORBER, RR BUMPER	1.00	122.60		122.60
20	8	T58307-48120 PANEL SUB-ASSY, BODY	1.00	1006.40		1006.40
21	9	T48691-48030 DAMPER, SUSPENSION	1.00	1343.10		1343.10
22	0	T64716-48020 C0 COVER, DECK TRIM, RR	1.00	438.30		438.30
23	1	T58410-48120 C0 BOARD ASSY, DECK	1.00	885.50		885.50
24	2	T64779-48060 TRAY, SPARE WHEEL	1.00	782.20		782.20
25	3	T67005-48350 PANEL SUB-ASSY, BACK	1.00	2378.00		2378.00
26	4	T67881-48070 WEATHERSTRIP, BACK	1.00	441.30		441.30
27	5	T68105-48905 GLASS SUB-ASSY, BACK	1.00	1230.40		1230.40
28	6	T75575-48040 MOULDING, BACK	1.00	51.90		51.90

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
		Lubrication/Fluid	Amount Due
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967			
			Document No. 0					
			Document Date 27/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/----	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
29	7	T67750-48010 C0 BOARD ASSY, BACK			1.00	578.50		578.50
30	8	T69350-48063 LOCK ASSY, BACK DOOR			1.00	974.00		974.00
31	9	T69430-48030 STRIKER ASSY, BACK			1.00	41.40		41.40
32	0	T90975-02071 EMBLEM,SYMBOL			1.00	57.90		57.90
33	1	T75442-48140 PLATE, BACK DOOR			1.00	73.70		73.70
34	2	SPZQ31-13020 Badge Assy, Engine Mark RHS			1.00	17.52		17.52
35	3	T76801-48510 A0 GARNISH SUB-ASSY,			1.00	1055.20		1055.20
36	4	T81561-48421 LENS & BODY, RR			1.00	667.70		667.70
37	5	T81551-48431 LENS & BODY, RR			1.00	667.70		667.70
38	6	T81591-48261 LENS & BODY, RR			1.00	506.70		506.70
39	7	T81581-48251 LENS & BODY, RR			1.00	506.70		506.70
40	8	T52563-48010 RETAINER, RR BUMPER,			1.00	121.10		121.10
41	9	T52562-48010 RETAINER, RR BUMPER,			1.00	121.10		121.10
42	0	L81920-48012 REFLECTOR ASSY,			1.00	60.40		60.40
43	1	T81910-48012 R/RR BPR REFLECTOR ASSY,			1.00	60.40		60.40
44	2	T89341-58060 A0 SENSOR, ULTRASONIC,			4.00	481.90		1927.60
45	3	T89348-58070 A0 RETAINER, ULTRASONIC			4.00	21.30		85.20
46	4	T89348-58120 RETAINER, ULTRASONIC			4.00	16.00		64.00
47	5	T89997-30100 ANTENNA, ELECTRICAL			1.00	72.60		72.60
48	6	T21000-20 SIKA 182010 SIKA TACK GO! (BLA			2.00	108.00		216.00
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total	
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less	
							Amount Due	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr Hoe Soon Kheng 15 Fernvale Close #18-26 Singapore 797477 Mobile: 98392967			
			Document No. 0					
			Document Date 27/09/2021					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2018	ASU60R	ANTGT P1	26/05/2018	SMA7877G	0	21286	67/TP/SMA7877G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEKB3GH50J002140		8ARZ122346	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
49	7	T21000-22 SIKA 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
50	8	T17408-46020 BAFFLE SUB-ASSY,			1.00	154.20		154.20
51	9	T17430-36550 PIPE ASSY, EXHAUST			1.00	767.00		767.00
For & on behalf of		Customer's Signature		Charge Summary		Total		29,612.92
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		GST 7.00%		2,072.90
				Labour		Less		0.00
				Sublet				
				Lubrication/Fluid				
				Others				
						Amount Due		31,685.82

Customer Copy