

Not Authen
Pehmy B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7956R

AAD2109-112

Vehicle No.:

27 SEP 2021

Chassis No.:

SHB7956R

Vehicle Make:

JTDKB3FU303083033

Vehicle Model:

TOYOTA

Date of Accident :

PRIUS

Third Party Insurer :

24/09/2021

Date of Registration :

126.

30/08/2019

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$ 1,300.70 ✓
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$ 193.50 X
1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$ 390.60 X
1 WEATHERSTRIP, FRONT DOOR, LH	\$ 231.30 X
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$ 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$ 97.50 X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$ 13.30 ✓
1 TAPE, BLACK OUT, NO.2 FRT LH	\$ 43.50 ✓
1 TAPE, BLACK OUT, NO.3 FRT LH	\$ 26.30 ✓
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$ 926.00 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$ 238.30 X
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$ 594.80 ✓
1 PANEL SUB-ASSY, QUARTER, LH	\$ 871.50 X
1 RETAINER, REAR BUMPER SIDE, LH	\$ 116.50 X
1 FENDER SUB-ASSY, FRONT LH	\$ 977.80 ✓
1 LINER, FRONT FENDER, LH	\$ 202.50 X
1 EMBLEM, SIDE PANEL	\$ 54.60 ✓

TOTAL	\$ 6,389.30
25%	\$ 1,597.33
	\$ 4,791.98

Special Nett

1 FENDER CLIP	\$ 65.00 X
1 FENDER LINDER CLIP	\$ 65.00 X
1SET DOOR WEATHERSTRIP CLIP	\$ 65.00 X

Trans-cab Auto Services Pte Ltd

AAD2109-112

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7956R

1 FRT DOOR STICKER TRANSCAB
1 TYRE
1 RIM *pr*
1SET CLIP, ROCKER PANEL MOULDING
TOTAL

\$ *na* 100.00 *born*
\$ *na* 350.00 *X*
\$ *na* 1,879.40 *✓*
\$ *na* 65.00 *✓*
\$ 2,589.40

TOTAL PARTS \$ 7,381.38**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings
and other, to enable repair.

\$ *na* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary
Portion, Remove And Renewal Of Parts, Adjust And Realign
The Same

\$ 2,000.00 *400h*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *660h*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *60h*

To Check Electrical Lighting Concerned.

\$ 170.00 *20h*

TOTAL \$ 4,190.00**Over All Total \$ 11,571.38****(PART-BY-PART) Repair Days***20 days**3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: