

新合利服務公司
Sin Hup Lee Service Co.
 Block 1005 Bukit Merah Lane2 #01-20
 Singapore 159761
 Tel: 6278 2482 Fax: 6271 9802
 Email: sinhuplee@gmail.com
 Reg. No. 083995/00E

26 September 2021

Attn: Motor Claim Department
 AIG Asia Pacific Insurance Pte Ltd
 AIG Building
 78 Shenton Way #07-16
 Singapore 079120

SALINA BINTE MD SHARIF
 c/o Sin Hup Lee Service Co.
 Block 1005 Bukit Merah Lane 2 #01-20
 Singapore 159761

Dear Sir/Ms,

RE: Road Traffic Accident on 20 September 2021 at 229 Yishun Street 21 carpark, involving vehicle SLQ2M/SJE3562E

Quotation for Repair Vehicle No: SJE3562E (Third Party Claim)

Quantity	List Item	Price
1	Head Lamp LH <i>/ CUT</i>	\$ 588.00 <i>/</i>
1	Front Bumper <i>/ OD</i>	\$ 768.00 <i>706</i>
1	Fog Lamp Cover <i>/ CUT</i>	\$ 156.00 <i>127</i>
1	Fender <i>X R</i>	\$ 486.00 <i>X</i>
1	Fender Side Bracket LH <i>/ BR</i>	\$ 52.00 <i>13</i>
1	Fog Lamp <i>1 X NO</i>	\$ 268.00 <i>X</i>
		\$ 2,318.00
		Less 25% <i>22</i>
		\$ 579.50
		\$ 1,738.50
		<i>1434 - 20% = 1147.20</i>
		<i>650</i>
		\$ 600.00 <i>200</i>
		\$ 550.00 <i>450</i>
		Total Amount \$ 2,888.50

Labour

- To repair, remove & re-fix damaged parts, straighten and realign affected areas
- To spray paint work on affected areas

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.

Thank you.

Yours Faithfully
 Mr Wong
 81122116

LEK Auto Consultants hence notify the Reparer of the following:

- To resurvey 1st time after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

= 1797.20
L/S - 1437.76
= 1450