



Vfix Auto Pte Ltd
25 Chindong Road
Singapore 615577
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 65026869
GEN / GST REG No.: 201530761P

ESTIMATE

DATE : 29/9/2021

Attention: Motor Claim Department

SHEET NO. 1 OF 1 SHEET

RE : VEHICLE NO : XD9336S (PENG CHUAN ENGINEERING CONSTRUCTION PTE LTD)

S/NO.	QTY	DESCRIPTION	UNIT \$S	AMOUNT \$S
1	2	REAR MUDGUARD <i>BT</i>	1,500.00	3,000.00
2	8	REAR MUDGUARD BRACKET <i>BT</i>	150.00	900.00
3	2	REAR MUDFLAP <i>CRH</i>	250.00	500.00
4	1	REAR CENTER PANEL <i>BT</i>		2,650.00
5	2	TAILLAMP <i>OR</i>	200.00	400.00
6	2	TAILLAMP PANEL <i>BT</i>	150.00	300.00
7	1	TAILGATE RUBBER <i>X</i>		350.00
				\$ 8,100.00
LESS 10%				\$ 7,290.00

S/NO.	QTY	DESCRIPTION	UNIT PRICE	AMOUNT \$S
1	1	SPECIAL NET		\$ 30 60.00
2	1	BODY SEALANT <i>OR</i>		\$ 25 25.00
3	1	REAR NUMBER PLATE <i>BT</i>		\$ 25 25.00
3	1	REAR NUMBER PLATE HOLDER <i>BT</i>		\$ 60.00

S/NO.	QTY	LABOUR & MISCELLANEOUS:	AMOUNT \$S
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	\$ 1,500.00 <i>500</i>
1	1	To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials	\$ 1,000.00 <i>400</i>
1	1	Towing Fees	\$ 120.00 <i>X</i>
1	1	To check, reconnect, repairing all the wiring	\$ 120.00 <i>30</i>
			\$ 2,740.00

GRAND TOTAL : \$ 10,090.00

ISSUED BY

weng sheng

KOH WENG SHENG

ESTIMATE CONFIRMED AND ACCEPTED BY

NAME, SIGNATURE, DATE SIGNED

Steve (CLKK)

HL AL
L/S
My AL Sy
4 L/S

LKA Auto Care Centre licence notify
the following of the following:

- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle
- The vehicle is not a motor vehicle

Acknowledged by Repaired:

Signature:

Date: