

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Nov 2021

Preliminary Advice

Insured Vehicle No	: GBA4355X	Accident Date	: 27/09/2021
TP Vehicle No	: SBV2231Y	Assignment Date	: 29/09/2021
Make	: HONDA AIRWAVE	Est. Duration of Repair	: 5
Date of Inspection	: 30/09/2021		
Inspection At	: CARWAY ENTERPRISE (HQ) 53 UBI AVE 1 #03-01 PAYA UBI IND. PARK SINGAPORE 408934		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,269.00
Revised Amount	:S\$	4,446.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,446.80
Lump Sum Repair	:S\$	2,700.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.