

RE: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

ALexKam <Alex_kam@leeshengauto.com.sg>

Wed 24/11/2021 10:13 AM

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Hi Denise ,

I already tell Rasul , This vehicle no before alignment report , The under carriage damage too serious . Cannot detect by wheel alignment machine .

Thanks

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]**Sent:** Wednesday, 24 November, 2021 8:58 AM**To:** ALexKam**Subject:** Re: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

hi,

Do you have the before alignment report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>**Sent:** Monday, 15 November 2021 4:20 pm**To:** ALexKam <Alex_kam@leeshengauto.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>**Subject:** Re: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

hi,

Do you have the before alignment report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: [6256-3561](tel:6256-3561) | email: denisetay@lkkauto.com | fax: [6256-4315](tel:6256-4315)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ALexKam <Alex_kam@leeshengauto.com.sg>**Sent:** Thursday, 11 November 2021 2:14 pm

To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>
Subject: RE: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

Hi Denise ,

Please refer to the attachment .

Thanks

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]
Sent: Monday, 8 November, 2021 10:11 AM
To: Rasul (LKKAuto); ALEXKam
Subject: Re: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

Hi Alex,

any updates on the alignment report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 3 November 2021 8:26 am
To: Rasul (LKKAuto) <Rasul@lkkauto.com>; ALEXKam <Alex_kam@leeshengauto.com.sg>
Subject: Re: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

Hi Alex,

any updates on the alignment report?

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, 1 November 2021 9:21 am
To: ALEXKam <Alex_kam@leeshengauto.com.sg>
Cc: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

Hi Alex,

email me the alignment copy

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)
Save the Earth. Print only when necessary.

-----Original Message-----

From: ALexKam [mailto:Alex_kam@leeshengauto.com.sg]
Sent: Sunday, 31 October, 2021 3:27 PM
To: Rasul (LKKAuto)
Subject: RE: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)

-----Original Message-----

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Friday, 29 October, 2021 10:01 AM
To: Alex Kam
Subject: RE: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z
(TAX/08/21/2055)

Hi Alex,

Kindly provide me the undercarriage photos the new and old parts because this case is under part by part

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Alex Kam [mailto:cjkam_leesheng@singnet.com.sg]
Sent: Tuesday, 12 October, 2021 8:48 PM
To: Yeo Poh Suan(Auto Svcs/Maint & Engg/ARC); Rasul (LKKAuto)
Subject: RE:BEFORE PAINTING PHOTO FOR VEHICLE NO SHF283Z (TAX/08/21/2055)