

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0793/2021/ZK  
DATE : 28-Sep-21  
WIP : 46322

\$6379.36

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/9/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Xiao Chen*

OWNER'S NAME : MS TAN XIUYUN (CHEN XIUYUN)  
ADDRESS : 34 UPPER CROSS STREET  
#12-146  
SINGAPORE 050034  
TELEPHONE : HP +65 98734833  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100494510-04  
VEHICLE NO : SLJ 7016 P  
MODEL CODE : A3 SEDAN 1.0 TFSI  
MODEL YEAR : 21/12/2016  
ENGINE NO : CHZ 138878  
CHASSIS NO : WAUZZZ8VXH1013682  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 27-Sep-21  
PLACE OF ACCIDENT : JUNCTION OF MARINA BLVD AND  
MARINA GARDEN DR



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 7016 P**

| S/N                  | NATURE OF JOBS                                                                                                                                                                    | ESTIMATED CHARGES        | SURVEYOR'S RECOMMENDATIONS |
|----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY S/N S                                                | 360.00                   | x                          |
| 2                    | TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES. S/N S                                                                    | <del>350.00</del> 280    | ✓                          |
| 3                    | TO DISMANTLE AND REINSTALL BUMPER. TO RENEW LHS FRONT FENDER AND LHS FRONT DOOR. TO REPAIR LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED S | <del>3,150.00</del> 1500 | ✓                          |
| 4                    | TO RESPRAY LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLE AND LHS SILL PANEL S                                                                              | 3,500.00                 | 1100 ✓                     |
| 5                    | TO CARRY OUT DIAGNOSTIC CHECK S/N S                                                                                                                                               | 192.00                   | ✓                          |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                   | : \$ 7,552.00            |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAZ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 7016 P

|                      |                                                      |     | DAMAGED PARTS & PRICES |           |
|----------------------|------------------------------------------------------|-----|------------------------|-----------|
| S/N                  | PARTS DESCRIPTION                                    | QTY | S/NETT                 | REMARKS   |
| 1                    | FRONT FENDER - LH <i>Dented</i>                      | 1   | \$ 851.00              | ✓ 680.40  |
| 2                    | POP RIVET <i>new Nec</i>                             | 5   | \$ 17.00               | ✓ 13.20 ✓ |
| 3                    | FRONT WHEEL HOUSING LINER - LH                       | 1   | \$ 169.00              | +         |
| 4                    | FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>for</i> | 1   | \$ 89.00               | +         |
| 5                    | FRONT DOOR - LH <i>Dented</i>                        | 1   | \$ 3,039.00            | ✓ 2431.20 |
| 6                    | FRONT DOOR OUTER SEAL - LH <i>new</i>                | 1   | \$ 161.00              | ✓ 128.40  |
| 7                    | BONDING AGENT <i>3 new</i>                           | 1   | \$ 49.00               | ? X       |
| 8                    | CLEANING SOLUTION                                    | 1   | \$ 68.00               | ? X       |
| 9                    | APPLICATOR <i>3 new</i>                              | 1   | \$ 8.00                | ? X       |
| 10                   | FRONT DOOR CATCH <i>new</i>                          | 1   | \$ 105.00              | ? X       |
| 11                   | SIDE MIRROR MOUNTING - LH <i>new</i>                 | 1   | \$ 1,024.00            | +         |
| 12                   | STONE CHIP <i>new</i>                                | 1   | \$ 180.00              | +         |
| 13                   | SUNDRIES <i>new</i>                                  | 1   | \$ 300.00              | ? 54.16 ✓ |
| TOTAL SPARE PARTS    |                                                      | :   | \$ 6,060.00            |           |
| TOTAL LABOUR CHARGES |                                                      | :   | \$ 7,552.00            |           |
| GRAND TOTAL          |                                                      | :   | \$ 13,612.00           |           |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.





55, UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian Lj  
 SURVEYED DATE : 20/09/21.  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS : Not authorised, OS Rep. H/S

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT