

Hui Zhen (LKK Auto)

From: Hui Zhen (LKK Auto)
Sent: Thursday, 7 October 2021 9:55 AM
To: enquiry@sh-motor.com; SUR
Subject: OD / SGY 7775L / DOA 26/9/2021

Dear Sir/Mdm,

As instructed by our client, please proceed to repair the **insured vehicle SGY 7775L at repair cost not more than \$19K on Lumpsum basis or whichever lower, (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Hui Zhen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: huizhen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)