

PECEIVED 2 1 FEB 2018 MOTOR CLAIM

Date

: 19 February 2018

To

: NTUC Income Insurance Co-operative Limited

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attn

: Ms Juliana Lee

AJAX Inspection Services Pte Ltd

120 Lower Delta Road #08-08, Cendex Centre Singapore 169208 Tel: +65 6255 0808 Fax: +65 6849 9155 info@ajaxinspection.com

Invoice No - AV13269

Company Reg No -201318067R GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/0963221-002

OUR REF : AVS2017-12762/WH

TP VECHILE NO : FBL1182P

CLAIM TYPE : PRE-REPAIR SURVEY

DATE OF SURVEY : 06 October 2017

No.	Description		Amount (S\$)
1	Professional fee		50.00
		Subtotal	50.00
		GST 7.00%	3.50
		Total	53.50

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows: Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com

AJAX Inspection Services Pte Ltd



PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Juliana Lee

Assign Date:

06/10/2017

Survey Date:

06/10/2017

Accident Date:

26/09/2017

TP Policy No:

TBA

Our Ref:

Claim Type:

AVS2017-12762/WH

Place of Survey:

Equator Brotherhood

Your Ref:

MT/0963221-002

Third Party

25 Kaki Bukit Road 4 #03-79 Synergy @ KB Singapore

Veh. No: Colour:

FBL1182P

Make/Model:

Honda CDR1000

Engine Capacity:

TBA

Multi-colored Engine No: Chassis No:

417800

TBA TBA

Odometer:

8902

Reg. Date:

TBA

Condition of Vehicle:

Description of Vehicle:

General: Handbrake: Good NA

Modification: Footbrake:

No NA Steering:

Paint work:

NA Good

Tyre Make:

Bridgrstone

Front Tyre Size:

120/70/R17

Front Side:

4mm

Rear Tyre Size:

195/50/R17 Rear Side:

4mm

Description of Damage:

The vehicle sustained damage on the front, rear and right portion.

The exhaust pipe, front fairing, engine cover, headlamp cowling, front mudguard and handle bar were among the items affected.

Remarks:

Based on visual survey of the vehicle without any repair estimate provided, we viewed that the repair cost should not be more than \$\$7,000.00 and could take approximately five (5) working days to complete.

All the stated damage are subject to consistency of the mentioned accident.

COMPLETED 14 FEB 2018

Adjuster:

Lee/Wee Ho

Motor Appraiser

Date

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Pre-repair survey - 06/10/2017













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Pre-repair survey













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AV\$2017-12762/WH

Your Ref:

MT/0963221-002

Re-survey items - 28/11/2017













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Re-survey items













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd



Our Ref:

AVS2017-12762/WH

Your Ref:

MT/0963221-002

Post repair survey - 25/01/2018









AJAX

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd