

# COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 1-Oct-21

LKK-Guo Qiang

MODEL: Hyundai Ioniq

INSURANCE: AIG ASIA (CP/P)

VEHICLE NO.: SHC8511D

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Wing Mirror LH / <i>cut</i>	1		\$1,391.70
	Front Fender LH / <i>free</i>	1		\$588.80
	Front Fender Blue-Drive LH / <i>abc</i>	1		\$26.60
	Front Bumper X <i>repair</i>	1		\$430.90
	Front Bumper Upper Moulding X <i>same</i>	1		\$368.50
	Front Bumper Grille LH X	1		\$93.45
	Front Bumper Clips / <i>abc</i>	10	\$2.20	\$22.00
	Front Wheel Cap LH / <i>scr</i>	1		\$346.40
	<b>SUB TOTAL</b>			\$3,268.35
	<b>LESS 20%</b>			\$653.67
	<b>DISCOUNTED TOTAL</b>			<b>\$2,614.68</b>
	<b>Labour Charge</b>			
	Panel Beating			\$800.00
	Spray Painting			\$800.00
	Tuff Kote			\$40.00
	<b>TOTAL LABOUR</b>			<b>\$1,640.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$4,254.68</b>

*350*  
*600*  
*✓*

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*4 Days.*

*4/5*

*After repair photos*

*Can Qiang*

*1/10/21*

### LKK Auto Consultants hence notify

#### the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: