



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS21010177/Kuf3e2	
			Date: 18/11/2021	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	ER 5005A
	Policy No.	SP2000085397-01	Coverage (\$)	0.00
	Claim No.	2021 20002869-GK	Excess (\$)	20,000.00
	Assign From	SHANTI	Assign Date	01/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	ROLLS ROYCE PHANTOM (A)	c.c	6749
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	SCA687S08KU103131	Colour	M. P. BLUE / WHITE
	Odometer	32273 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/45 R22	CONTINENTAL	8 mm
	L/H Front Tyre	255/45 R22	CONTINENTAL	8 mm
	R/H Rear Tyre	285/40 R22	CONTINENTAL	6 mm
	L/H Rear Tyre	285/40 R22	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	28/09/2021	Inspection Date	04/10/2021
	Survey held at	Blk 10 Ang Mo Kio Industrial Park 2A, #01-05		
	Repairer	OPTIMA WERKZ PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$1,250,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	