



18 OCT 2021

Your Ref : SNM21D205614/C02/SMZ370R/TANCHC  
Our Ref : TP/11802/FBQ7277J/SMZ370R

BY EMAIL

CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD  
#16-00 SPRINGLEAF TOWER  
SINGAPORE 079909

ATTN: Ms. Jacqueline Tan

Dear Jacqueline,

**Accident involving FBQ7277J & SMZ370R on 22/09/2021**

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

|                                     |                  |
|-------------------------------------|------------------|
| 1. Cost of Repair (Inc 7% GST)      | \$ 597.06        |
| 2. Loss of Use (3 days x \$20)      | \$ 60.00         |
| 3. GIA Vehicle Insurance Search Fee | \$ 2.00          |
| <b>TOTAL</b>                        | <b>\$ 659.06</b> |

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

**BAN HOCK HIN CO PTE LTD**

.....  
Raymond Tan  
Manager/Insurance Dept  
Tel : 6821 6520 ext. 220  
Fax : 6284 2969  
Email : [raymond@bhh.com.sg](mailto:raymond@bhh.com.sg)





**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE  
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL  
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

## TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

CHINA TAIPING INSURANCE (S) PTE LTD  
105 CECIL STREET  
#18-00 / 19-00  
THE OCTAGON  
S'PORE 069534  
MOTOR CLAIMS DEPT

Invoice No. : **DLCR40108588-I11802**  
Invoice Date : 15/10/2021  
Payment Due Date : 14/11/2021

CLAIM NO. : 11802  
POLICY NO. : V0107634-VMF  
VEHICLE NO. : FBQ7277J  
MAKE/MODEL : /

| S/N               | Description                       | Action         | Qty | Unit Price  | Amount   |
|-------------------|-----------------------------------|----------------|-----|-------------|----------|
| 1                 | REPAIR ON REAR BOX                | Repair         | 1   | \$84.00     | \$84.00  |
| 2                 | RUBBER SEAL REAR BOX              | REPLACE        | 80  | \$0.50      | \$36.00  |
|                   |                                   |                |     | Disc %: 10% |          |
| 3                 | SPRAY PAINT ON REAR BOX           | Spray          | 1   | \$250.00    | \$250.00 |
| 4                 | STICKER (SINGAPORE POST) BOX REAR | REPLACE        | 1   | \$70.00     | \$63.00  |
|                   |                                   |                |     | Disc %: 10% |          |
| 5                 | LABOUR                            | Supply/Install | 1   | \$125.00    | \$125.00 |
| SUB TOTAL         |                                   |                |     |             | \$558.00 |
| GST @ 7 %         |                                   |                |     |             | \$39.06  |
| GRAND TOTAL (SGD) |                                   |                |     |             | \$597.06 |

Validity: 30 days

For & on Behalf of  
BAN HOCK HIN CO PTE LTD

  


Printed by : RAYMOND

bizSAFE<sub>3</sub>



## INSURER ENQUIRY

## Find insurer

Vehicle reg. no.

SMZ370R

Date of Accident

22/09/2021 

Reset

## % RESULT &amp; RECEIPT

## TP Insurer Enquiry

Insurance ..... China Taiping Insurance (Sing...

Period of Insurance ..... 07/04/2021 - 06/04/2022

Requested By ..... Tan Chok Lok (Ban Hock Hin C...

Requested Date ..... 02/10/2021 13:19

## Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

## General Insurance Association

Records Management Centre

GST Registration No: **M400017735**