



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY		Ref: CC4/ASM21010211/Upa3q2 Date: 27/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SCV 7373B	Veh. Inspected	SLP 7920Y
Policy No.	GA579703	Coverage (\$)	0.00
Claim No.	S1M03J5V	Excess (\$)	0.00
Assign From		Assign Date	04/10/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31243860	Colour	RED
Odometer	56339 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/50 R18	MICHELIN	7 mm
L/H Front Tyre	225/50 R18	MICHELIN	7 mm
R/H Rear Tyre	225/50 R18	DUNLOP	7 mm
L/H Rear Tyre	225/50 R18	DUNLOP	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	01/10/2021	Inspection Date	04/10/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	