



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM21010218/Ktce2 Date: 24/11/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SKJ 8709D	Veh. Inspected	SLW 4542M	
Policy No.	GA547971	Coverage (\$)	0.00	
Claim No.	S1M03J9E	Excess (\$)	0.00	
Assign From	TEO KITTY	Assign Date	04/10/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 2 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JM6DJ2HAA01200243	Colour	METALLIC GREY	
Odometer	38597 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	185/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	3 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	3 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	02/10/2021	Inspection Date	05/10/2021	
Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>3 Working Days</b>	