

ESTIMATED ACCIDENT REPAIR COST



ACCIDENT TIME REPORTED	20:46HRS
ACCIDENT DATE	27-Sep-21
BUS CAPTAIN NAME	CHONG CHEE HOE
THIRD PARTY CLAIM AGAINST	India International Insurance Pte Ltd

BUS REGISTRATION NUMBER	SG5980B
BUS TYPE (SD/DD)	DD
BUS ROUTE NUMBER	
BUS ADVERTS (Y/N)	N

SECTION 1 : PARTS & CONSUMABLE ITEMS (MATERIAL COST)

NO.	Part or Item Description	Quantity	Total Cost
1	TOWER TRANSIT LOGO (B) <i>m /</i>	1	\$120.00
2	MATERIAL COST <i>m /</i>	1	\$309.98
		7% GST	\$30.10
		PARTS TOTAL COST	\$460.08

429.98

SECTION 2 : ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT)	TOTAL COST
TO PERFORM REPAIR WORKS ON :-	
• REAR ENGINE DOOR ASSY	320 \$1,300.00
SPRAY PAINTING :-	
• REAR ENGINE DOOR	\$640.00
SPRAY PAINTING \$640 PER PANEL	7% GST \$135.80
LABOUR CHARGES \$650 PER DAY	LABOUR TOTAL COST \$2,075.80

Rasul
Hy 9000068
3 days
05/10/21 @ 1035

960

SECTION 3 : NUMBER OF DAYS BUS IN WORKSHOP FOR SURVEY & REPAIRS

Reg after repair
email: rasul@lkkauto.com

BUS TYPE (SD / DD)	DD
LOSS OF USE COST	

DATE IN	
DATE & TIME SURVEY	
DATE OUT	
TOTAL NUMBER OF DAYS	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

429.98
 960.00
 1389.98

SUMMARY	
SECTION NO.	COST
1	\$460.08
2	\$2,075.80
3	\$0.00
TOTAL	\$2,535.88