

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd  
64 Cecil Street, #04-00 IOB Building  
Singapore 049711

**Our File No:** CS/III21010239/KUF3E2

**Date:** 11/10/2021

### REFERENCE

Insured/Claimant:	GRABS RENTAL PTE LTD	Policy No:	D21MFL0000447	
Date of Loss:	01/10/2021	Nature of Claim:	OD	Claim No: N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8461M		
Make & Model:	HONDA VEZEL, 1.5 HYBRID X (A)	Engine No:	LEB5955764
Reg. Date:	29/08/2017 (Man. Year: 2017)	Chassis No:	RU31255747
Colour:	Metallic Grey	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$62,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Triangle 8 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	Triangle 8 mm	Rear Right Side:	KAPSEN 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	05/10/2021		
Date Inspected:	05/10/2021	Inspected At:	385 Sin Ming Drive Repairer: Esteem Performance Pte Ltd
Estimated Period of Repair:	0.0 days		

**Adjuster:** KENNETH KONG

**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$62,000.00
OMV :	\$24,914.00
PARF Rebate (1) :	\$ 3,750.00
Quota Premium Paid :	\$47,501.00
COE Rebate (2) :	\$28,002.00
Total Rebate (1) + (2) = :	\$31,752.00

The total amount incurred will be Market Value \$62,000.00 minus Total Rebate \$31,752.00 = \$30,248.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8461M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >