



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E


MR INDIA INTERNATIONAL INSURANCE PTE LTD	POLICY NO	: D19MCV0000229_02
64 CECIL STREE	OUR REF	: OD 3474
#04/05/06-02	VECHICLE NO	: YN 3402 J
IOB BUILDING	MAKE/MODEL	: MIT FE83
SINGAPORE 049711	CHASSIS	: FE83BEA20939
ATTN: MOTOR CLAIMS DEPT	DATE OF ACCIDENT	: 01.10.21

SURVEY BY

DATE : 04.10.21

1 PC	FRONT WINDSCREEN GLASS		S\$	1,338.08
1 PC	FRONT WINDSCREEN GLASS RUBBER			387.00
1 PC	FRONT WINDSCREEN PILLAR RH			1,240.95
1 PC	WIPER ARM, WIPER BLADE, WIPER COVER			129.82
1 PC	WIPER GRILLE			383.26
1 PC	WIPER GRILLE "CANTER" STICKER			84.37
1 PC	FRONT CORNER PANEL RH			398.41
1 PC	FRONT CORNER PANEL LOWER RUBBER RH			25.92
1 PC	SIDE MIRROR RH			107.67
1 PC	SIDE MIRROR BRACKET RH			252.90
1 PC	SIDE MIRROR COVER RH			64.03
1 PC	FRONT PANEL			1,115.92
1 PC	FRONT GRILLE			383.26
1 PC	FRONT GRILLE EMBLEM			57.12
1 PC	FRONT GRILLE "FUSO" EMBLEM			107.24
8 PCS	FRONT GRILLE CLIPS	8.00		80.00
1 PC	HEADLAMP ASSY RH			721.25
1 PC	HEADLAMP LOWER RUBBER RH			15.00
1 PC	SIGNAL LAMP RH			206.01
1 PC	SIDE LAMP RH			139.05
1 PC	FRONT BUMPER			999.86
1 PC	FRONT BUMPER BRACKET			151.71
1 PC	FRONT DOOR RH			1,910.15
1 PC	FRONT DOOR OUTER GARNISH RH			51.35
1 PC	FRONT DOOR TOP MOULDING RH			100.15
1 PC	FRONT DOOR OUTER MOULDING RH			120.00
2 PCS	FRONT DOOR HINGES	131.60		263.20
1 PC	FRONT DOOR WEATHERSTRIP RH			408.22
1 PC	FRONT DOOR INNER TRIM BOARD RH			541.25
1 PC	FRONT DOOR INNER LOCK RH			535.76
1 PC	FRONT DOOR REGULATOR GEAR WITH MOTOR)			1,028.59
1 PC	FRONT DOOR JACK RH			78.60
1 PC	FRONT DOOR STEP GARNISH RH			415.44
1 PC	FRONT DOOR FRAME RUBBER RH			222.83
1 PC	FRONT FENDER WHEEL ARCH GARNISH RH			68.04
				S\$ 14,132.41
LESS 25%				3,533.10
				S\$ 10,599.31

----- P/G 2



進友成汽車服務私人有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

CON'T FROM PAGE-1

	S\$	10,599.31	
1 PC DASHBOARD	S\$	740.19	
1 PC DASHBOARD REINFORCEMENT		580.49	
1 PC METER ASSY		1,380.69	
1 PC METER TOP GARNISH		220.69	
1 PC STEERING WHEEL INNER COVER		155.60	
1 PC STEERING WHEEL OUTER COVER		177.90	
1 PC CABIN MOUNTING		480.50	
1 PC BRAKE BOOSTER PUMP		1,845.78	
1 PC BRAKE OIL RESERVOIR		245.64	
	S\$	5,827.48	
	LESS	25%	
		1,456.87	
	S\$	4,370.61	
1 PC ERP BRACKET	S\$	26.00	S/NETT
1 PC FRONT NO. PLATE		30.00	"
1 PC BRAKE OIL		60.00	"
	S\$	116.00	
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS	S\$	120.00	
TO DISMANTLE AND REFIX DASHBOARD FITTING		300.00	
TO TRANSFER DOOR FITTING		100.00	
TO REMOVE ROOF LINING, CUSHION SEAT & CARPET		120.00	
TO TOP-UP AIR-CON GAS		120.00	
TO CHECK WIRING FUNCTION		50.00	
LABOUR CHARGES		1,800.00	
TO PUTTY AND SPRAY PAINTING CHARGES		1,200.00	
	S\$	18,895.92	

SIN DOLLARS: EIGHTEEN THOUSAND EIGHT HUNDRED NINETY-FIVE AND CENTS NINETY-TWO ONLY

YOUR FAITHFULLY,


CYS AUTOMOBILE SERVICES PTE LTD