

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SH7226C

Date: 30/09/2021

Make : HYUNDAI

Insurance: CHINA TAIPING

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
1	REAR BUMPER COVER / <i>nc</i>			\$1,106.00	✓
1	REAR BUMPER CLIPS / <i>nc</i>			\$22.00	✓
	REAR BUMPER BRACKET LH RH <i>X NN</i>		\$35.60	\$71.20	
1	REAR BUMPER REINFORCEMENT <i>X NN</i>			\$428.40	
1	REAR BUMPER SPONGE <i>X NN</i>			\$119.50	
1	RR BUMPER REINFORCEMENT BRACKET LH RH <i>X NN</i>		\$160.60	\$321.20	
1	BOOTLID / <i>BT</i>			\$2,174.90	✓
1	BOOTLID 'H' EMBLEM / <i>nc</i>			\$63.10	✓
1	BOOTLID CRDI PLATE / <i>nc</i>			\$52.40	✓
1	BOOTLID MOULDING <i>X NN</i>			\$85.00	✓
1	BOOTLID I40 EMBLEM / <i>nc</i>			\$67.90	✓
1	BOOT LID LAMP LH RH <i>X NN</i>		\$622.20	\$1,244.40	
SUB TOTAL				\$5,756.00	3486.3
LESS 20%				\$1,151.20	
DISCOUNTED TOTAL				\$4,604.80	2789.04
1	REAR BUMPER REVERSE SENSOR <i>X NN</i>			\$135.70	Nett
1	REAR BUMPER ADVERTISEMENT LOGO / <i>nc</i>			\$50.00	Nett ✓
1	BOOTLID COMFORT LOGO & TEL NO. STICKER / <i>nc</i>			\$60.00	Nett ✓
Labour Charge				\$245.70	Nett
	PANEL BEATING			\$600.00	<i>300</i>
	SPRAY PAINTING CHARGE			\$600.00	<i>250</i>
	CHECK ALL LIGHTING			\$60.00	<i>X NA</i>
	REMOVE/REFIX REVERSE SENSOR			\$60.00	<i>40</i>
TOTAL LABOUR				\$1,320.00	
ESTIMATE TOTAL				\$6,170.50	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

40 days

3999.04

-20%: 3200

L/S

After repair photos

Gmo R/S

01/10/21 12pm