

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationale Des Experts En Automobile					
Α	XA INSURANCE I	PTE LTD	Ref:	CS/ASM21010252/Uvy3e2		
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	13/10/2021		
А	ATTN: LOH CYNTH	IIA	Code:	ASM		
1.	Policy Particulars :- THIRD PARTY CLAIM					
lı	nsured Veh.	SHF 678T	Veh. Inspected	SKS 5128C		
P	Policy No.	VFX/P2413997	Coverage (\$)	0.00		
C	Claim No.	S1M03IUM	Excess (\$)	0.00		
A	Assign From	LOH CYNTHIA	Assign Date	05/10/2021		
2. Vehicle Particulars & Condition						
N	Make & Model	HONDA MOBILIO (A)	c.c	1497		
E	Engine No.	HIDDEN	Year of Reg.	2015		
C	Chassis No.	MRHDD4870FP000032	Colour	WHITE		
	Odometer	159008 KM	Steering	IN ORDER		
E	Brakes	IN ORDER	Modification	SPORTS RIM		
G	General	GOOD				
3. Conditions of Tyres						
		Size	Make	Balance		
F	R/H Front Tyre	195/60 R15	YOKOHAMA	7 mm		
L	_/H Front Tyre	195/60 R15	YOKOHAMA	7 mm		
F	R/H Rear Tyre	195/60 R15	YOKOHAMA	7 mm		
L	_/H Rear Tyre	195/60 R15	YOKOHAMA	7 mm		
4.	Description of Damages					
Т	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
A	Accident Date	26/09/2021	Inspection Date	07/10/2021		
S	Survey held at	SIANG HUI MOTOR WORKS				
		BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
<del>55.</del>			ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days			