



OPTIMA WERKZ

SINGAPORE

OPTIMA WERKZ PTE LTD
Co. Reg. No. 201212455W
www.ow.sg

f /OptimaWerkz

© /OptimaWerkz

Date: 05/10/2021
Vehicle No: SMX5283L
Model: MERCEDES BENZ E200 SEDAN
Chassis: WDD2120342B267264-2015
Reg. Year: 2016

Third Party Insurer: AIG
Third Party Veh No: SKM3959R
Date of Accident: 03/10/2021
Estimator: TING AN
Surveyor:

*Not Notified
11 Sep 3305ch
Recovery After Rain
2 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>1712</i>	1		<i>Pr</i> \$1,920.00
2	REAR BUMPER SIDE RETAINER LH	1		<i>Pr</i> \$58.00
3	REAR BUMPER INNER GUIDE LH	1		<i>CM</i> \$66.00
4	REAR BUMPER LOWER DIFFUSER	1		<i>PER/CA</i> \$340.00
5	REAR BUMPER LOWER CHROME MOULDING <i>218</i>	1		<i>ngcm</i> \$470.00
6	REAR EXHAUST CRHOME TIP LH <i>287</i>	1		<i>not</i> \$330.00
7	REAR TAIL LAMP LH	1		<i>ngcm</i> \$700.00
8	REAR END PANEL	1		REPAIR
9	REAR BOOTLID	1		REPAIR
SUB TOTAL				\$3,884.00
LESS 10%				-\$388.40
PARTS TOTAL				\$3,495.60

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Pr</i> \$50.00
2	REAR BUMPER REVERSE SENSOR	1		<i>Pr</i> \$300.00
S/N TOTAL				\$350.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$700.00 *250*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR BOOTLID, REAR END PANEL & ETC.

\$700.00 *250*

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

\$120.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

na \$100.00 *X*

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.

\$80.00 *150*

LABOUR TOTAL \$1,700.00

VIC / TING AN

TOTAL \$5,545.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 1313

Branch

9A Serangoon North Ave 5 Singapore 554500

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011



Acknowledged by Repairer

Signature:

Date: