




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: LOH CYNTHIA			Ref: CS3/ASM21010274/Vuy3e2 Date: 14/10/2021 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 3407E	Veh. Inspected	SJN 7501H
	Policy No.	VFX/P2419138	Coverage (\$)	0.00
	Claim No.	S1M03JD7	Excess (\$)	0.00
	Assign From	LOH CYNTHIA	Assign Date	05/10/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CITY	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MRHGM26509P020281	Colour	WHITE
	Odometer	129773 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm
	L/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm
	R/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm
	L/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	03/10/2021	Inspect Date / Time	06/10/2021 (05:00 PM)
	Survey held at	2 KAKI BUKIT AVENUE 2 #02-02 KAKI BUKIT S417921		
	Repairer	MW BROTHERS AUTO REPAIRS		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM21010274/Vuy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or
relying on this Report, in whole or in part, does so at his or her own risk.