

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

\$17920.32

Xiao Chen

OWNER'S NAME	:	MR YU QIAN
ADDRESS	:	232 COMMONWEALTH AVENUE #08-21 SINGAPORE 149740
TELEPHONE	:	HP +65 97436846
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	7210002173
VEHICLE NO	:	SMX 4006 C
MODEL CODE	:	A5 SB 2.0 TFSI
MODEL YEAR	:	11/1/2021
ENGINE NO	:	DEM 027753
CHASSIS NO	:	WAUZZZF56MA015362
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	29-Sep-21
PLACE OF ACCIDENT	:	Alexandra Rd & Delta Rd

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 4006 C

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X 250
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1500 ✓
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS FRONT DOOR.	\$ 4,000.00	1650 1600
6	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 8,552.00	

[Handwritten signature]

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>crack</i>	1 S	2,342.00 ✓	1873.60
2	FRONT BUMPER SECURING STRIP <i>new</i>	2 S	71.00 +	
3	FRONT BUMPER GRILLE <i>new</i>	1 S	196.00 +	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>crack</i>	1 S	262.00 +	209.20 ✓
5	FRONT BUMPER AIR GUIDE - LH <i>new</i>	1 S	63.00 +	
6	FRONT BUMPER CLOSING ELEMENT <i>crack</i>	1 S	262.00 +	209.20 ✓
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1 S	135.00 +	
8	FRONT BUMPER LOWER TRIM - LH	1 S	48.00 +	
9	FRONT BUMPER LOWER TRIM - CENTER <i>new</i>	1 S	114.00 +	
10	RADIATOR GRILLE <i>crack</i>	1 S	1,694.00 ✓	1355.20
11	FOAM FILLER PIECE <i>crack</i>	1 S	146.00 ?	116.40 ✓
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	1 S	845.00 →	X
13	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1 S	36.00 +	
14	FRONT BUMPER TOP COVER <i>new</i>	1 S	127.00 +	
15	"CAUTION" STICKER <i>new</i>	1 S	14.00 +	
16	"A/C" STICKER	1 S	8.00 +	
17	LOCK CARRIER TOP BRACKET <i>crack</i>	1 S	137.00 +	109.60 ✓
18	LOCK CARRIER SUPPORT BRACKET - LH / RH	2 S	58.00 +	
19	FRONT PARKING AID SENSOR - FRONT OUTER	1	TBC	+
20	FRONT PARKING AID SENSOR - FRONT INNER	1	TBC	+
TOTAL SPARE PARTS		:	\$ 6,558.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHA1@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT PARKING AID SEAL RING	4	\$ 14.00 +	
22	HORN - LH	1	\$ 126.00 +	
23	HORN BRACKET - LH	1	\$ 29.00 +	
24	BONNET <i>Dented</i>	1	\$ 3,312.00 ✓	2649.60
25	BONNET ATTACHMENT PARTS <i>Not nec</i>	1	\$ 123.00 +	
26	BONNET IMPACT PROTECTION - CENTER	1	\$ 28.00 -	22
27	BONNET IMPACT PROTECTION - LH / RH	2	\$ 56.00 -	43.68
28	BONNET STRIKER - LH	1	\$ 50.00 +	
29	BONNET LID LOCK	1	\$ 214.00 +	
30	BONNET LOCK COVER	1	\$ 44.00 +	
31	FRONT FENDER - LH <i>Buckled</i>	1	\$ 1,060.00 ✓	848
32	FRONT FENDER ATTACHMENT PARTS - LH	1	\$ 53.00 +	
33	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 74.00 +	
34	FRONT FENDER BRACKET - LH <i>Not nec</i>	1	\$ 35.00 ?	X
35	FRONT FENDER BRACE - LH <i>Not nec</i>	1	\$ 118.00 ?	X
36	FRONT FENDER FLEDGE COVER - LH LONG	1	\$ 36.00 +	
37	FRONT FENDER FLEDGE COVER - LH SHORT	1	\$ 16.00 +	
38	FRONT WHEEL HOUSING LINER - LH	1	\$ 275.00 +	
39	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	1	\$ 169.00 +	
40	FRONT WHEEL SPOILER - LH <i>*torn</i>	1	\$ 73.00 +	58.40
SUB TOTAL SPARE PARTS		:	\$ 5,905.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORAKHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 4006 C

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER TRIM - LH <i>Nec</i>	1	\$ 164.00 ✓	130.80
42	LED HEADLIGHT - LH <i>cracked.</i>	1	\$ 7,685.00 ✗	6148 ✓
43	LIFT CYLINDER - LH <i>Nec Nec</i>	1	\$ 198.00 ✗	
44	LIFT CYLINDER HOSE - LH	1	TBC ✗	
45	RADIATOR AIR GUIDE - LH	1	\$ 31.00 ✗	
46	RADIATOR AIR GUIDE - LH	1	\$ 16.00 ✗	
47	RADIATOR AIR GUIDE - UPPER	1	\$ 16.00 ✗	
48	FRONT DOOR CHROME TRIM - LH	1	\$ 164.00 ✗	
49	FRONT NO PLATE <i>Dented</i>	1	\$ 60.00 ✓	
50	SUNDRIES <i>Nec.</i>	1	\$ 300.00 ✓	18.40 ✓
TOTAL SPARE PARTS		:	\$ 21,097.00	
TOTAL LABOUR CHARGES		:	\$ 8,552.00	
GRAND TOTAL		:	\$ 29,649.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NCRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :


EXCESS COST :

LIABILITY :

REMARKS :

Adrian L
05/10/21

are authorised, 06 Days.



PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT