



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ONG KIAN THENG DERICK			Ref: CS/ASM21010291/Auy3e2 Date: 25/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 513U	Veh. Inspected	SKF 4985U	
Policy No.	GA264143	Coverage (\$)	0.00	
Claim No.	S1M03JDY	Excess (\$)	0.00	
Assign From	ONG KIAN THENG DERICK	Assign Date	06/10/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA ODYSSEY	c.c	2354	
Engine No.	HIDDEN	Year of Reg.	2012	
Chassis No.	JHMRB3850CC200445	Colour	SILVER	
Odometer	267148 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	FALKEN	6 mm	
L/H Front Tyre	215/55 R17	FALKEN	6 mm	
R/H Rear Tyre	215/55 R17	FALKEN	6 mm	
L/H Rear Tyre	215/55 R17	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/10/2021	Inspection Date	06/10/2021	
Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	