

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

Cecilia.

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST2100256
Date: 05 Oct 2021
Veh Reg No: SLW7672B
Make/Model: HONDA CIVIC 1.6 VTI CVT
Chasis No: MRHFC5650JT000414
Reg. Date: 02/05/2018
Your Ref No: SNB8901X

Claim Type: Third Party
Accident Date: 01/10/2021
TP Veh Reg No: SNB8901X

Estimate Repair Cost to Vehicle No :SLW7672B

Quantity	Description	List Price S\$	Amount S\$
List Price			
1	1 PC FRT FENDER LH <i>Distorted</i>	520.70 ✓	
2	1 PC FRT FENDER COWLING LH <i>Deformed</i>	99.20 ✓	
3	1 PC FRT LH FENDER SIGNAL LAMP <i>ut</i>	58.30 ✓	
4	1 PC HEADLAMP LH <i>cracked</i>	758.20 ✓	
5	1 PC HEADLAMP RETAINER LH <i>cracked</i>	31.20 ✓	
6	1 PC HEADLAMP PANEL LH <i>Repair</i>	124.20 <i>x</i>	
7	1 PC FRT GRILLE <i>ut</i>	102.70 ✓	
8	1 PC FRT GRILLE EMBLEM <i>new</i>	28.90 ✓	
9	1 PC FRT HEADLAMP LH TOP CHROME <i>new</i>	156.20 ✓	
10	1 PC FRT GRILLE CHROME	188.70 <i>x</i>	
11	1 PC FRT GRILLE TOP TRIM	103.80 <i>x</i>	
12	1 PC FRT GRILLE TOP RUBBER	61.30 <i>x</i>	
13	1 PC FRT SUPPORT PANEL	566.20 <i>x</i>	
14	1 PC FRT SUPPORT PANEL TOP TRIM <i>new new</i>	121.10 <i>x</i>	
15	1 PC FRT BUMPER <i>Distorted</i>	669.90 ✓	
16	1 PC FRT BUMPER REINFORCEMENT <i>Deformed</i>	470.30 ✓	
17	1 PC FRT BUMPER LH SIDE RETAINER <i>Damaged</i>	28.90 ✓	
18	1 PC FRT FOG LAMP COVER LH <i>ut</i>	66.10 ✓	
19	1 PC FRT BUMPER SIDE BRACKET LH <i>Best</i>	51.20 ✓	
20	1 PC ISONATOR BOX <i>cracked</i>	102.70 ✓	
21	1 PC FRT FENDER INNER BRACKET LH <i>Best</i>	68.10 ✓	
		4,377.90	
Less 20%		875.58	3,502.32
Special Net			
22	1 SET FRT FENDER COWLING CLIPS LH <i>new</i>	40.00 <i>30</i>	
23	1 SET FRT GRILLE CLIPS <i>new</i>	40.00 <i>20</i>	
24	1 SET FRONT GRILLE TOP RUBBER CLIPS <i>new new</i>	30.00 <i>x</i>	
25	1 SET FRT SUPPORT PANEL TOP TRIM CLIPS	30.00 <i>x</i>	
26	1 SET FRT BUMPER CLIPS <i>new</i>	60.00 <i>30</i>	

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST2100256**
Date: 05 Oct 2021
Veh Reg No: **SLW7672B**
Make/Model: HONDA CIVIC 1.6 VTI CVT
Chasis No: MRHFC5650JT000414
Reg. Date: 02/05/2018
Your Ref No: SNB8901X

Claim Type: Third Party
Accident Date: 01/10/2021
TP Veh Reg No: SNB8901X

Estimate Repair Cost to Vehicle No :SLW7672B

Quantity	Description	List Price	Amount
		SS	SS
27	1 SET FRT BUMPER INNER COVER CLIPS <i>Not new</i>	30.00 x	
28	1 4 LITRES RADIATOR COOLANT <i>Not new</i>	100.00 x.	
		330.00	330.00
	Labour		
29	1 TO CHECK WIRING	50.00 <i>30.</i>	
30	1 TO REFILL AIRCON GAS	120.00 x	
31	1 TO CHECK WHEEL ALIGNMENT	120.00 <i>80.</i>	
32	1 TO REMOVE AND REFIT CROSSMEMBER TO REPLACE RESONATOR	350.00 <i>200.</i>	
33	1 TO REMOVE AND REFIT RADIATOR	150.00 x	
34	1 TO REMOVE AND REFIT AIR CON CONDENSER	150.00 x	
35	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 <i>700.</i>	
36	1 TO SPRAY PAINTING <i>1680</i>	1,000.00 <i>650.</i>	
37	1 TO SPRAY UNDERSEAL	100.00 <i>30.</i>	
		3,040.00	3,040.00
	Total		S\$ 6,872.32
	Add GST @ 7%		481.06
	Total Amount Payable		S\$ 7,353.38

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND THREE HUNDRED FIFTY THREE AND CENTS THIRTY EIGHT ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time

LKK Auto which may be required after work has begun.
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

06

Admin
P/P 05/10/21
05 Days
total: 4255.84 P/P
4255.84