

ORIGINAL PRICE DISC. % NETT

To replace front bumper and attachments, bonnet, front air duct, rear bumper and attachments, tail end panel, trunk floor, making good the boot lid include pulling and straightening on accident areas and knocking out dents caused by the accident

~~7,920.00~~
6480

To spray paint front bumper, bonnet, rear bumper, tail end panel, trunk floor plate and boot lid

~~4,800.00~~ 3840

To check electrical wiring systems and lightings at the front and rear section for proper function

~~360.00~~ 280

To supply front emboss number plate

70.00 / 9600

To remove and install boot compartment carpet and garnish to facilitate repairs

~~225.00~~ 180

To replace rear exhaust silencer include alignment of system and conducting checks for leak

~~450.00~~ 360

To replace boot lid smart opener system include programming and conducting checks for proper function

~~450.00~~ 360

To replace LH/RH high intensity headlight include functionality programming and conducting checks for proper function

~~900.00~~ 720

To carry out body cavity preservation (For cut panel)*

~~900.00~~ 720

To carry out body cavity preservation

~~100.00~~

To transfer PDC from old to new bumper include reconnecting and conducting checks for proper function

~~150.00~~ 80

To replace PDC wire harness and connectors include resetting and conducting checks for proper function

~~360.00~~ 250

3840

L/F GRILLE *su* ?
 L/FOG LAMP BRACKET -
 L/F OUTER TRIM ?
 L/INN PARK SENS RING *ne*
 L/R BUMP CORN ATTACH
 L/R BUMPER SEAL *ne*
 L/R INN PARKING SENS *cn*
 L/R OUT BUMPER GUIDE ?
 L/R OUT PARKING SENS ?
 L/R REFLECTOR *bu*
 LOCK MOTOR X
 LOWER FRONT BUMPER *de* ?
 LWR AIR INTAKE GRILL *cn*
 LWR RR BUMPER COVER *de*
 OUTER REAR PANEL *bf*
 OUT PANEL EMC SCREW *ne*
 R/AIR INLET GRILLE ?
 R/BUMPER AIR GRILLE -
 R/CTR PARK SENS RING *ne*
 R/F BUMPER SUPPORT ?
 R/F GRILLE *su* ?
 R/FOG LAMP BRACKET ?
 R/F OUTER TRIM -
 R/R BUMP CORN ATTACH ?
 R/R BUMPER SEAL *ne* ?
 R/R INN PARKING SENS - ?
 R/R OUT BUMPER GUIDE ?
 R/R OUT PARKING SENS ?
 R/R REFLECTOR X
 REAR BADGE *ne*
 REAR BUMPER COVER *de* ?
 REAR BUMPER SUPPORT
 REAR SCREEN *de* *photo - old & new*
 REAR SCREEN BOND KIT *ne*
 REAR SCREEN BUFFER *ne* ?
 RR BUMPER ATTACHMENT
 RR LWR BUMPER COVER *de*
 RR LWR BUMPER TRIM *de*
 RR TOWING EYE COVER X
 T-GATE LOCK STRIKER X

144.6	1.00	144.6
88.7	1.00	88.7
53.25	1.00	53.25
5.05	1.00	5.05
108.75	1.00	108.75
8.69	1.00	8.69
248.7	1.00	248.7
159.94	1.00	159.94
248.7	1.00	248.7
80.5	1.00	80.5
586.65	1.00	586.65
171.57	1.00	171.57
67.79	1.00	67.79
253.86	1.00	253.86
1140.05	1.00	1140.05
8.25	1.00	8.25
51.95	1.00	51.95
67.79	1.00	67.79
5.05	1.00	5.05
9.47	1.00	9.47
144.6	1.00	144.6
88.4	1.00	88.4
53.25	1.00	53.25
108.75	1.00	108.75
8.69	1.00	8.69
248.7	1.00	248.7
159.94	1.00	159.94
248.7	1.00	248.7
80.5	1.00	80.5
69.5	1.00	69.5
967.01	1.00	967.01
528.89	1.00	528.89
1174.8	1.00	1174.8
131.55	1.00	131.55
24	1.00	24
159.94	1.00	159.94
151.19	1.00	151.19
328.01	1.00	328.01
40.2	1.00	40.2
55.75	1.00	55.75

UPP AIR VENT GRILLE *can*
 LH FRONT HEADLAMP *can*
 RH FRONT HEADLAMP *can*
 REAR SILENCER *lt*
 HEAT SHIELD *lt*
 REAR BUMPER LOWER DIFFUSER *lt*

Total Labour : 19,085.00
 Total
 Parts : 28,399.87
 Total Labour & Parts : 47484.87

GST
 @7%: 3,323.94
 Grand
 Total : 50,808.81

58.11
 4,942.15
 4,942.15
 2,383.85
 259.00
 191.05

1.00
 1.00
 1.00
 1.00
 1.00
 1.00

Reval
90010068

17 days

07/10/21 @ 1140

Resurvey before paint

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: