

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP21-089

Date : 28/09/2021

Vehicle Num. : SLB2669E

Make/Model : Subaru Forester-2016

Chassis/Eng# : JF1SJGK85GG067865/FA20A874603

Accident Date : 27/09/2021

Claim No. :

Reference :

Policy No. :

Cecilia

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 pc	LIST ITEMS :		795.40
2.	1 pc	Frt Bumper Assy <i>beh d.</i>		50.10
3.	1 pc	Frt Bumper Bracket RH <i>ku</i>		61.30
		Frt Wiper Cover RH <i>ku n</i>		
		List Total S\$:	<i>845.50</i>	906.80
		20.00% Discount S\$:	<i>676.40</i>	181.36
				725.44
		LABOUR :		
		To remove, repair and replaced damaged bodyparts,		200.00
		realign bodyworks & where consistent to the accident	<i>400</i>	
		To putty and respray painting on affected area.		400.00 <i>200</i>
		Labour Total S\$:		600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 1,325.44

=====

SUCCESS UNITED PTE LTD

Adrian Lj

h/s 06/10/21

02 days

total: 1076.40

h/s: 850