

1	of 2 ?	100%	Find Next
---	--------	------	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref: CS/III21010323/Utf3	
64 CECIL STREET		Date: 07/10/2021	
#05-02 IOB BUILDING SINGAPORE 049711		Code: III2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.	Veh. Inspected	SLW 2813U	
Policy No. D20MPC0000663-01	Coverage (\$)	0.00	
Claim No.	Excess (\$)	0.00	
Assign From BHUVANESWARI	Assign Date	07/10/2021	
2. Vehicle Particulars & Condition			
Make & Model	c.c	0	
Engine No. HIDDEN	Year of Reg.		
Chassis No.	Colour		
Odometer -	Steering		
Brakes	Modification		
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date 06/10/2021	Inspection Date 07/10/2021		
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		
5a. Remarks			
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			