

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/AIG21010331/AQF3E2

**Date:** 02/12/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700079826  
Claimant Vehicle No : SJA4456T Insured Vehicle No : SLT9678M  
Date of Loss: 27/09/2021 Nature of Claim: TP Claim No: 8984656606SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJA4456T**  
Make & Model: SUZUKI SWIFT, 1.2 (A) Engine No: K12B1011544  
Reg. Date: 10/12/2007 (Man. Year: 2007) Chassis No: ZC71S411372  
Colour: Black Odometer: 179808 km  
Engine Capacity: 1242 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15  
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm  
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 07/10/2021  
Date Inspected: 06/10/2021 Inspected At: Automobile Hub Enterprise  
1 Kaki Bukit Avenue 6, #02 -11 Autobay @ Kaki Bukit  
Singapore 417883  
Estimated Period of Repair: 0.0 days

**Adjuster:** ADRIAN LING

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**TOTAL LOSS ASPECT**

Market Value :	\$9,000.00
OMV :	\$8,799.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$20,997.00
COE Rebate (2) :	\$4,829.00
Total Rebate (1) + (2) = :	\$4,829.00

The total amount incurred will be Market Value \$9,000.00 minus Total Rebate \$4,829.00 = \$4,171.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

# REPAIR DETAILS

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**