

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

8/10/21 10am

SURVEYOR COPY

M/S : TAY RONG JIE, MATTHEW
29A HILLVIEW AVE #03-09

SINGAPORE 669562

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 05/10/2021
TP Veh Reg No: EH95A

Estimate No: MC1902204
Date: 06 Oct 2021
Policy No: 21-MT104295-R03
Veh Reg No: SJG8753C
Make/Model: MITSUBISHI LANCER
1.6 A

Not Notified
11 Sep @
Repair After Rain
3 days

Estimate Repair Cost to Vehicle No :SJG8753C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 TAILAMP LH	1 PC	<i>CR</i> 421.00	<i>✓</i>
2 TAILAMP GROMMET INNER LH	1 PC	<i>na</i> 5.00	<i>✓</i>
3 TAILAMP GROMMET OUTER LH	1 PC	<i>na</i> 5.00	<i>✓</i>
4 TAILAMP PANEL LH	1 PC	<i>R</i> 62.00	<i>✓</i>
5 REAR BUMPER	1 PC	<i>Bu</i> 697.00	<i>✓</i>
6 REAR BUMPER SIDE RETAINER LH	1 PC	<i>R</i> 50.00	<i>✓</i>
7 REAR BUMPER CLIPS	5 PC	<i>na</i> 25.00	<i>✓</i>
8 REAR BUMPER RIVET	18 PC	<i>na</i> 90.00	<i>✓</i>
9 REAR BUMPER GROMMET	2 PC	<i>na</i> 10.00	<i>✓</i>
10 REAR BUMPER REINFORCEMENT	1 PC	209.00	<i>✓</i>
11 REAR SPLASH SHIELD LH	1 PC	<i>na</i> 28.00	<i>x</i>
12 REAR END PANEL	1 PC	<i>R</i> 495.00	<i>x</i>
13 REAR AIR VENT LH	1 PC	<i>na</i> 28.00	<i>x</i>
		2,125.00	
	Less 20%	425.00	1,700.00
LABOUR			
14 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>200</i>
15 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>na</i> 60.00	<i>x</i>
16 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, REAR FENDER LH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	<i>3000</i>
17 TO SPRAY REAR BUMPER, REAR FENDER LH, REAR END PANEL	1 PC	600.00	<i>4000</i>
		1,300.00	1,300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: