BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Pax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944

(AfterSales) (Motorrad) Fax. 64796601 64796624

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 59714 Page No. : 1 of 5

Date Estimated : 06/10/2021

Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -- ACCOUNT -219

Ong Chew Hoon India Int'L Insurance Pte Ltd 99 Yishun Avenue 1

64 Cecil Street #04-05 IOB Building Singapore 049711

Singapore 769139

#09-37

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE

SMT9157M	WBA5F32020FH99036 23,	/07/2020	320i	Sedan	*****		23822
	DESCRIPTION				***************************************		VALUE
	To replace rear bumper including to knock the accident	k out dented ar	ea cause	d by			1,275.00
	To respray rear bumper						1,038.00
	To remove old PDC assembly, replace da reconnect to new bumper including conduproper function.		nd				177.00
	To check electrical wiring system and ligh rear section for proper function.	iting at the					177.00
	Sundries.						80.00
					Tot	al Labour 1:	2,747.00
	DESCRIPTION			QT	<u>Y</u>	PRIC	VALUE
	# TAILPIPE TRIM CHROME D=90MM				1	125.85	125.85
	Mount, lateral				1	199.95	199.95
	REAR BUMPER CARRIER				1	493.80	493.80
	# TRIM STRIP (SPORT) # REAR RH TRIM PANEL				1	104.20	104.20
	REAR BUMPER LH SIDE GUIDE				1	75.25	75.25
	REAR BUMPER RH SIDE GUIDE				1	134.30	134.30
	# REAR BUMPER PANEL PRIMED (SP				1	134.30 1,281.30	134.30
	REAR BUMPER TOWING EYE COVER	PRIMED			1	48.10	1,281.30 48.10
	REAR RH REAR REFLECTOR				1	39.05	39.05
					Tot	al Parts :	2,636.10



BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941

Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 [AfterSal 64796624 [Motorrad

(AfterSales) (Motorrad)



GST REG. NO: M2 - 0020081 - X

ESTIMATE

Estimate No. Date Estimated

: b1 59714

: 06/10/2021

Prepared By

: Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SMT9157M

WBA5F32020FH99036

23/07/2020

320i Sedan

23822



Labour 1 2,747.00 Parts 2,636.10 Labour 2 0.00 Excess 0.00 Total GST @ 7% 376.82

Grand Total 5,759.92

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Q = 59714.



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time: 06 Oct 2021 / 15:57:05

Receipt Date/Time: 06 Oct 2021 / 15:57:05

Tax Invoice/Receipt

Receipt No.: ITNET-00000-211006-002750

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SMA3476G As at 06 Oct 2021/10:28:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Co: MSIG INSURANCE (SINGAP Insurance Enquiry - SMA3476G	ORE) PTE LTD			
1 Insurance Enquiry - SMA3476G Enquiry Fee 20211006155627697330		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	542125XXXXXX4416	eNETS Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.