

TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	05/10/2021
Vehicle Reg. No.:	SKZ4041M	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	VOLKSWAGEN GOLF, 1.4 TSI (A7) (5G13GZ) (A)	Vehicle Reg. Date:	21/01/2016
Vehicle Colour:	BLUE	Chassis No:	WWWZZZAUZFW357394
Engine No:	CXS258982		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	830.70
Miscellaneous Items	11.00
Labour	640.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	1,481.70
+ GST 7.00% (\$\$)	103.72
Nett Amount (\$\$)	1,585.42

This claim is handled by: JACELYN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must have surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 07 Oct 2021)
 Parts: 144 VOLKSWAGEN GOLF 1.4 TSI (A7) (5G13GZ) (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Mova Automotive Pte Ltd/SKZ4041M/07/10/2021 15:29
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*SIDE MIRROR GLASS RH	10.00	0.00	*194.00 FL
2	1		*SIDE MIRROR COVER RH	10.00	0.00	*154.00 FL
3	1		*SIDE MIRROR HOUSING RH	10.00	0.00	*575.00 FL
4	1		*FRONT DOOR RH - REPAIR	10.00	0.00	-
Sub Total (\$\$)						923.00
- List Item Discount on L Items (\$\$)						92.30
Total Parts (\$\$)						830.70

F=Franchise part, L=ListItemDisc.

Mova Automotive Pte Ltd/SKZ4041M/07/10/2021 15:29. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$) 11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO KNOCK & STRAIGHTEN ON FRONT DOOR RH.TO REMOVE & REPLACE DAMAGED ITEMS, REALIGN CONNECTION	New	200	280.00
2	TO INSPECT LIGHTING MECHANISM & CHECK WIRING	New	30	80.00
3	TO SPRAY PAINT ON REPAIRED AREAS	New	250	280.00

Gross Labour Cost (\$\$) 640.00

Mova Automotive Pte Ltd/SKZ4041M/07/10/2021 15:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P- 830.70

N- 11

L- 480

P/P - 1321.70

Steve (LKK)

8/19/21, 11.00am

WHL PL

1 day

P/P

My Bel sy