

Borneo Motors

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 Pandan Crescent
Singapore 126462. Tel no. : 6631 1388



Steve (LKK)
11/10/21, 1030am

WHL PL
7 dji
P/P
M B/L M

LKK
Summer
+60197356879
11/10 - 10am.

ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1 Document No. 0 Document Date 07/10/2021	Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052 Mobile: 91802425

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBW1GG402181753	2AR1878569	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS: LONPAC INS ACC DATE: 06.10.2021 T/P VEH: XE3720A DATE IN: DATE SURVEY: DATE AUTHORIZE:				50 100.00
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, BONNET, FRONT SUPPORT, RHS FRONT FENDER, FRONT DOOR, REAR DOOR AND FIX NEW PARTS 3-5 x 866				3031 6062.00
3	B	BP-RES3 TO SPRAY PAINT ON WHOLE FRONT PORTION INCL FRONT SUPPORT AND BOTH RHS DOORS 4 x 742				2968 5936.00
4	B	BP-LAB3 TO REMOVE AND RE-INSTALL AIR COND CONDENSER, RADIATOR ETC TO ENABLE REPAIR (NETT) ?				866.00
5	B	BP-LAB3 TO REMOVE AND REPLACE RHS HEADLAMP. CHECK AND FOCUS HEADLIGHTS (NETT)				216.50

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Acknowledged by Repairer
Signature:
Date:

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 126462. Tel no : 6631 1388

ESTIMATE

Account Details		Account No.		Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1		Mr Tan Lay Hai				
		Document No. 0		52 New Upper Changi Road #13-1486 Singapore 461052				
		Document Date 07/10/2021		Mobile: 91802425				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
6	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO ENABLE REPAIR (NETT)						216.50 ✓
7	Z	BP-SLANT SUPPLY BONNET SEALANT (NETT)						100.00 ✓
8	Z	BP-SLANT SUPPLY FRONT SUPPORT SEALANT (NETT)						100.00
9	B	BP-LAB3 TO REMOVE, RENEW AND BALANCE RHS FRONT TYRE AND RIM (NETT)						X 108.25
10	B	BP-LAB3 TO CARRY OUT WHEEL ALIGNMENT (NETT)						X 216.50
11	S	BP-SUBLET SUPPLY RHS FRONT TYRE						X 800.00
12	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.						
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total		
		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less		
						Amount Due		

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1368


ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLPH1		Mr Tan Lay Hai		
			Document No. 0		52 New Upper Changi Road #13-1486 Singapore 461052		
			Document Date 07/10/2021		Mobile: 91802425		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0	20227	61TP/SLV8363S/061021
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.					
14	1	L52119-3T910 COVER, FR BUMPER <i>BR</i>	1.00	968.20		968.20	
15	2	L52125-33120 BRACKET, FOG LAMP <i>BR</i>	1.00	170.10		170.10	
16	3	L52145-33070 STAY, FR BUMPER <i>BR</i>	1.00	58.00		58.00	
17	4	L52197-30040 BUMPER BRACKET, <i>BR</i>	2.00	7.80		15.60	
18	5	L52611-33280 ABSORBER, FR BUMPER <i>BR</i>	1.00	155.90		155.90	
19	6	L53155-33060 SEAL, RADIATOR <i>BR</i>	1.00	101.50		101.50	
20	7	L53879-30040 RETAINER, FR FENDER <i>BR</i>	2.00	12.40		24.80	
21	8	L81481-33060 COVER, FOG LAMP, RH <i>BR</i>	1.00	143.30		143.30	
22	9	L52021-33210 REINFORCEMENT <i>BR</i>	1.00	504.10		504.10	
23	0	L53301-33160 HOOD SUB-ASSY <i>BR</i>	1.00	2273.20		2273.20	
24	1	L53381-33100 SEAL, HOOD TO <i>BR</i>	1.00	49.80		49.80	
25	2	L53811-33230 FENDER, FR RH <i>BR</i>	1.00	1353.20		1353.20	
26	3	L53827-33070 PROTECTOR, FR FENDER <i>BR</i>	1.00	101.50		101.50	
27	4	L53835-33100 BRACE, FR FENDER TO <i>BR</i>	1.00	72.00		72.00	
28	5	L53837-33010 BRACKET, FR SIDE <i>BR</i>	2.00	20.70		41.40	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No. 2 Pandan Crescent
 Singapore 128462, Tel no: 6631 1388

ESTIMATE

Account Details		Account No. S1000007 / ICLP11		Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No. 0		Mr Tan Lay Hai 52 New Upper Changi Road #13-1486 Singapore 461052	
		Document Date 07/10/2021		Mobile: 91802425	
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers
2017	AVV60R	BEXGB S5	18/01/2018	SLV8363S	0
			Wip No.	Order No. / Remarks	
			20227	61TP/SLV8363S/061021	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In
JTHBW1GG402181753		2AR1878569	60	Carine Yeo C L	--/--/----
					0.00 --/--/----
					0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %
					Amount
29	6	T90467-07214 CLIP <i>nrc</i>	12.00	2.70	
30	7	L53875-33220 LINER,FR FENDER RH <i>TNI</i>	1.00	281.10	
31	8	L51441-33200 COVER, ENGINE UNDER, <i>?</i>	1.00	234.20	
32	9	L53201-33191 SUPPORT,RADIATOR <i>X</i>	1.00	1468.00	
33	0	L53208-33070 SUPPORT SUB-ASSY, <i>X</i>	1.00	153.60	
34	1	T90467-07217 CLIP <i>nrc</i>	9.00	2.60	
35	2	L53295-33080 SEAL,COOL AIR <i>?</i>	1.00	305.70	
36	3	L85315-33461 JAR, WASHER, A <i>?</i>	1.00	276.10	
37	4	L89341-78010 C1 SENSOR, ULTRASONIC, <i>X</i>	2.00	490.80	
38	5	L89341-78010 B2 SENSOR, ULTRASONIC, <i>1</i>	2.00	490.80	
39	6	L89348-35030 CLIP, ULTRASONIC <i>nrc</i>	2.00	4.40	
40	7	L89348-76010 CLIP, ULTRASONIC <i>nrc</i>	2.00	12.10	
41	8	L81210-48051 LAMP ASSY,FOG RH <i>nrc</i>	1.00	516.00	
42	9	L81105-33D11 HOUSING SUB-ASSY, <i>BR (HeadUp)</i>	1.00	6185.20	
43	0	L75535-33020 MOULDING,WINDSHIELD RH <i>?</i>	1.00	87.30	
44	1	L75545-30170 CLIP,WINDSHIELD <i>nrc</i>	10.00	10.70	
45	2	L75547-51021 ROOF DRIP MLDG CLIP, <i>nrc</i>	10.00	11.00	
46	3	L53111-33450 GRILLE, RADIATOR <i>?</i>	1.00	1180.90	
47	4	L53121-33080 MOULDING, RADIATOR <i>?</i>	1.00	375.80	
48	5	L42611-33B61 WHEEL, DISC <i>X</i>	1.00	2760.50	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary
			Please acknowledge receipt of vehicle		Total 36,847.75
			Parts 22,126.00		GST 7.00% 2,579.34
			Labour 13,921.75		Less 0.00
			Sublet 800.00		
			Lubrication/Fluid 0.00		
		Others 0.00		Amount Due 39,427.09	

Customer Copy