

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ABDUR RASHEED BIN ABDUL BUHARI	Cust No/Name / ABDUR RASHEED BIN ABDUL BUHARI
59 CHAI CHEE ROAD	Reg No/Reg Date SMV2732M / 24/09/202
#10-852	Date In/Mileage / 0
SINGAPORE 460059	Chassis No KNAF5416ML5064085
Contact No Mobile: 97858124	Engine No G4FGKH752958
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	08/10/2021/ 13:40		442 / CocoLu	40782			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1600.00
RENEW REAR BUMPER, BOOTLID, REAR END PANEL, REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH					490X2			800
E PNT88000								60.00
REMOVE & INSTALL PARKING SENSOR								9
E PNT88000								300.00
REMOVE & INSTALL REAR COMPARTMENT TRIMS								700
E PNT98000								2100.00
SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH					350X2			
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								40.00
C&C LOGO								
M SUNDRY								40
APPLY SEALANT FOR ACCIDENT PORTION								80.00
M SUNDRY								nec
Sundry								20.00
M SUNDRY								nn
PARKING SENSOR X 4								800.00
M COVER-RR BUMPER	BR				1.00	651.00	00.00	651.00
M COVER-RR BUMPER LWR	BR				1.00	241.00	00.00	241.00
M COVER-RR BUMPER FOG LAMP, RH	BR				1.00	88.00	00.00	88.00
M COVER-RR BUMPER FOG LAMP, LH	BR				1.00	88.00	00.00	88.00
M LAMP ASSY-SIDE T/SIGNAL, RH	BR				1.00	181.00	00.00	181.00
M LAMP ASSY-SIDE T/SIGNAL, LH	BR				1.00	181.00	00.00	181.00
M EXTN WRING ASSY-BWS	BR				1.00	207.00	00.00	207.00
M BRACKET-RR BEAM UPR MTG, RH	BR				1.00	9.00	00.00	9.00
M BRACKET-RR BEAM UPR MTG, LH	BR				1.00	9.00	00.00	9.00
M BEAM-RR BUMPER	BR				1.00	318.00	00.00	318.00
M BRACKET-RR BEAM LWR, CTR	BR				1.00	6.00	00.00	6.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the process of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ABDUR RASHEED BIN ABDUL BUHARI	Cust No/Name /ABDUR RASHEED BIN ABDUL BUHARI
59 CHAI CHEE ROAD	Reg No/Reg Date SMV2732M / 24/09/202
#10-852	Date In/Mileage / 0
SINGAPORE 460059	Chassis No KNAF5416ML5064085
Contact No Mobile: 97858124	Engine No G4FGKH752958
	Make/Model KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	08/10/2021/ 13:40		442 / CocoLu	40782			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM LWR MTG	✓ GR	X nn		1.00	6.00	00.00	6.00
M	ANTENNA ASSY-SMARTKEY	✓ BT	X nn		1.00	46.00	00.00	46.00
M	STAY-RR BUMPER RH	✓ BT	X nn		1.00	65.00	00.00	65.00
M	STAY-RR BUMPER LH	✓ BT	X nn		1.00	65.00	00.00	65.00
M	BRACKET ASSY-RR BPR SIDE UPR,L	✓ BT	X nn		1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR,R	✓ BT	X nn		1.00	31.00	00.00	31.00
M	PANEL ASSY-TRUNK LID	✓ BT	X nn		1.00	1297.00	00.00	1297.00
M	PANEL ASSY-BACK	✓ BT	X nn		1.00	324.00	00.00	324.00
M	W/STRIP-TRUNK LID OPNG	✓ BT	X nn		1.00	100.00	00.00	100.00
M	LATCH ASSY-TRUNK LID	✓ BT	X nn		1.00	112.00	00.00	112.00
M	TRIM ASSY-RR TRANSVERSE	✓ BT	X nn		1.00	41.00	00.00	41.00
M	EMBLEM-CERATO	✓ BT	X nn		1.00	28.00	00.00	28.00
M	EMBLEM-GT LINE	✓ BT	X nn		1.00	45.00	00.00	45.00
M	LOGO ASSY-KIA SUB	✓ BT	X nn		1.00	32.00	00.00	32.00

Estimate

Steve CLKK
8/10/21, 3:00pm

DD- M-A AL
EXCER-?
P/P
My B/L sy
5 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

7% GST on **9,346.00** **654.22**
Total Payable 10,000.22

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or bank transfer. You agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing.