



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
ABDUR RASHEED BIN ABDUL BUHARI 59 CHAI CHEE ROAD #10-852 SINGAPORE 460059 Contact No Mobile: 97858124	Cust No/Name	/ABDUR RASHEED BIN ABDUL BUHARI
	Reg No/Reg Date	SMV2732M / 24/09/202
	Date In/Mileage	/ 0
	Chassis No	KNAF5416ML5064085
	Engine No	G4FGKH752958
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	08/10/2021/ 13:40		442 / CocoLu	40782			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, BOOTLID, REAR END PANEL, REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH								1600.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR								60.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS								300.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH								2100.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								120.00
M SUNDRY C&C LOGO								40.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION								80.00
M SUNDRY Sundry								20.00
M SUNDRY PARKING SENSOR X 4								800.00
M	COVER-RR BUMPER				1.00	651.00	00.00	651.00
M	COVER-RR BUMPER LWR				1.00	241.00	00.00	241.00
M	COVER-RR BUMPER FOG LAMP,RH				1.00	88.00	00.00	88.00
M	COVER-RR BUMPER FOG LAMP,LH				1.00	88.00	00.00	88.00
M	LAMP ASSY-SIDE T/SIGNAL,RH				1.00	181.00	00.00	181.00
M	LAMP ASSY-SIDE T/SIGNAL,LH				1.00	181.00	00.00	181.00
M	EXTN WIRING ASSY-BWS				1.00	207.00	00.00	207.00
M	BRACKET-RR BEAM UPR MTG,RH				1.00	9.00	00.00	9.00
M	BRACKET-RR BEAM UPR MTG,LH				1.00	9.00	00.00	9.00
M	BEAM-RR BUMPER				1.00	318.00	00.00	318.00
M	BRACKET-RR BEAM LWR,CTR				1.00	6.00	00.00	6.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
ABDUR RASHEED BIN ABDUL BUHARI 59 CHAI CHEE ROAD #10-852 SINGAPORE 460059 Contact No Mobile: 97858124	Cust No/Name	/ABDUR RASHEED BIN ABDUL BUHARI
	Reg No/Reg Date	SMV2732M / 24/09/202
	Date In/Mileage	/ 0
	Chassis No	KNAF5416ML5064085
	Engine No	G4FGKH752958
	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	KLK STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	08/10/2021/ 13:40		442 / CocoLu	40782		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	BRACKET-RR BEAM LWR MTG			1.00	6.00	00.00	6.00
M	ANTENNA ASSY-SMARTKEY			1.00	46.00	00.00	46.00
M	STAY-RR BUMPER RH			1.00	65.00	00.00	65.00
M	STAY-RR BUMPER LH			1.00	65.00	00.00	65.00
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	00.00	25.00
M	BRACKET-ASSY RR BPR SIDE UPR,R			1.00	31.00	00.00	31.00
M	PANEL ASSY-TRUNK LID			1.00	1297.00	00.00	1297.00
M	PANEL ASSY-BACK			1.00	324.00	00.00	324.00
M	W/STRIP-TRUNK LID OPNG			1.00	100.00	00.00	100.00
M	LATCH ASSY-TRUNK LID			1.00	112.00	00.00	112.00
M	TRIM ASSY-RR TRANSVERSE			1.00	41.00	00.00	41.00
M	EMBLEM-CERATO			1.00	28.00	00.00	28.00
M	EMBLEM-GT LINE			1.00	45.00	00.00	45.00
M	LOGO ASSY-KIA SUB			1.00	32.00	00.00	32.00

Confirm & accepted by

7% GST on **Nett** **9,346.00**
654.22

Total Payable **10,000.22**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.