

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 14 Oct 2021

Preliminary Advice

Insured Vehicle No	: XE3551X	Accident Date	: 08/10/2021
TP Vehicle No	: SMK5775C	Assignment Date	: 11/10/2021
Make	: AUDI A3	Est. Duration of Repair	: 19
Date of Inspection	: 12/10/2021		
Inspection At	: PREMIUM AUTOMOBILES PTE LTD - ALEXANDRA (HQ) 281 ALEXANDRA PTE LTD, LEVEL B2 SINGAPORE 159938		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	55,809.00
Revised Amount	:S\$	40,938.00
Check Items (Estimated)	:S\$	3,796.00
Total	:S\$	44,734.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note the the preliminary advice amount (Revised & Check items) stated are subject to consistency checks, part prices and labour cost.