

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0831/2021/TF
DATE : 11-Oct-21
WIP : 48529

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 13/10/2021

YOUR INSURED VEH NO : YP 9506 T

SOMPO INSURANCE SINGAPORE PTE LTD

50 Raffles Place

#05-01/06 Singapore Land Tower

Singapore 048623

Attn: Motor Claims Dept

Tel: 6461 6555 Fax 6221 3147

AlG.

OWNER'S NAME : MR SUBRAMANIAN ANANDHAN
ADDRESS : BLK 628 JURONG WEST ST 65
#13-398
SINGAPORE 640628
TELEPHONE : HP +65 9836 6394
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D20MTPV01014578
VEHICLE NO : **SKX 6386 R**
MODEL CODE : AUDI A3 SPORTSBACK 1.4 TFSI
MODEL YEAR : 21/12/2015
ENGINE NO : CZC 506002
CHASSIS NO : WAUZZZ8VXGA074139
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Oct-21
PLACE OF ACCIDENT : 8 BULIN AVE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKX 6386 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNES S/N	\$ 360.00	X
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. S/N	\$ 250.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	1000
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,902.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKX 6386 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delnd</i>	1	\$ 2,016.00	✓
2	RADIATOR GRILLE <i>lt</i>	1	\$ 691.00	✓
3	RADIATOR GRILLE COVER <i>pepper</i>	1	\$ 98.00	x
4	CAUTION STICKER <i>3 new</i>	1	\$ 14.00	✓
5	A/C STICKER	1	\$ 8.00	✓
6	BONNET <i>Dented</i>	1	\$ 2,745.00	✓
7	BONNET STRIKER <i>New</i>	1	\$ 110.00	x
8	BONNET EDGE PROTECTION <i>New</i>	1	\$ 28.00	✓
9	BONNET CATCH <i>3 new</i>	1	\$ 63.00	+
10	BONNET LOCK	1	\$ 214.00	+
11	BONNET BOWDEN CABLE <i>3 new</i>	1	\$ 58.00	+
12	BONNET BOWDEN CABLE COVER	1	\$ 10.00	+
13	FRONT BUMPER FORM PIECE <i>New</i>	1	\$ 83.00	+
14	FRONT BUMPER REINFORCMENT COVER <i>New</i>	1	\$ 56.00	+
15	HEADLIGHT - RH <i>new</i>	1	\$ 2,641.00	x
16	RADIATOR AIR GUIDE - UPPER CENTRE / RIGHT <i>New</i>	2	\$ 37.00	x
17	AIR DUCT COVER <i>2 new</i>	1	TBC	+
18	AIR DUCT	1	TBC	+
19	FRONT NO. PLATE <i>new</i>	S/N	\$ 60.00	✓
20	SUNDRIES <i>?</i>		\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 9,132.00	
TOTAL LABOUR CHARGES		:	\$ 4,902.00	
GRAND TOTAL		:	\$ 14,034.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lj
13/10/21

not Authorised, 04 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT