

## ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

Our Ref

305490147

Via Fax

EMAIL

Date

11 10 21

Your Insured

GBF 61374

Time of Fax

Date of Acc

16.01.80

Attn: Motor Claims Department

ALG

Dear Sirs

## SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3323 H

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if would call us to arrange for the survey of the vehicle:

& Lim Kwok Eng

Tel: 6214 8355 or HP: 9824 0811

♦ Jumani Bin Masudin

Tel: 6214 8315 or HP: 9635 5305

# Lim Tien Slong

Tel: 6214 8398 or HP: 9635 8546

Chiang Liat Choon

Tel: 6214 8314 or HF: 9296 6006

chianglc@cdge.com.sg Fax no. 6546 8156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\*** 

VEHICLE NO SHD3323H

DATE 08/10/21 07:25 PM

MAKE

06/10/17

CHIANG/AIG

MODEL TOYOTA PRIUS G4A

Qty	Parts Description/ Labour	Туре	Unit Price	Amount
9	REAR BUMPER			\$458.60
	REAR BUMPER LOWER COVER			\$552.60
3	REAR BUMPER REINFORCEMENT			\$318.80
8	REAR BUMPER UNDER SIDE COVER RH			\$232.60
3	REAR BUMPER TOW COVER			\$82.70
	REAR BUMPER SIDE RETAINER LH/RH			\$112.70
10	REAR BUMPER CLIP			\$22.00
	SUB TOTAL			\$1,780.00
	25.00%			\$445.00
	DISCOUNTED TOTAL		,	\$1,335.00
-	BUMPER MAT			\$50.00
1	BUMPER REVERSE SENSOR			\$135.70
		7.90		\$185.70
	Labour Charge		_	
	Panel Beating			\$500.00
	Spray Painting Charge			\$300.00
	Tuff Kote			\$60.00
	Remove/Refix Reverse Sensor			\$60.00
	TOTAL LABOUR			\$920.00
			?	,
	ESTIMATE TOTAL			\$2,440.70
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			