

**IR ESTIMATE\***

VEHICLE NO SHD3323H

DATE 08/10/21 07:25 PM

MAKE

06/10/17

CHIANG/AIG

MODEL

TOYOTA PRIUS G4A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			\$458.60
1	REAR BUMPER LOWER COVER			\$552.60
1	REAR BUMPER REINFORCEMENT			\$318.80
1	REAR BUMPER UNDER SIDE COVER RH			\$232.60
1	REAR BUMPER TOW COVER			\$82.70
1	REAR BUMPER SIDE RETAINER LH/RH			\$112.70
10	REAR BUMPER CLIP			\$22.00
	<b>SUB TOTAL</b>		1667.30	<b>\$1,780.00</b>
	<b>25.00%</b>		1250.47	\$445.00
	<b>DISCOUNTED TOTAL</b>			<b>\$1,335.00</b>
1	BUMPER MAT			\$50.00
1	BUMPER REVERSE SENSOR			\$135.70
			185.70	<b>\$185.70</b>
	<b>Labour Charge</b>			
	Panel Beating		350	\$500.00
	Spray Painting Charge		630	\$300.00
	Tuff Kote			\$60.00
	Remove/Refix Reverse Sensor		30	\$60.00
	<b>TOTAL LABOUR</b>			<b>\$920.00</b>
	<b>ESTIMATE TOTAL</b>		2066.17	<b>\$2,440.70</b>
			4581.650	
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 9749 5747  
 WP 11/10/21 C405  
 1/3 Rising after repair  
 Tanpin & Lkkauto.com  
 2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: