


Carvin

26/6/11

WIP: 48104

PREMIUM AUTOMOBILES

Kiam /



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. 5LF 6888 S

After Advair
- 9 days


DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Defhd</i>	1	\$ 1,362.00	✓
2	FRONT BUMPER CONNECTING PIECE	1	\$ 205.00	?
3	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 293.00	+
4	FRONT BUMPER SECURING STRIP - RH	1	\$ 38.00	?
5	FRONT BUMPER CLOSING ELEMENT - RH <i>Defhd</i>	1	\$ 113.00	✓
6	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 144.00	+
7	FRONT BUMPER SPOILER <i>torn</i>	1	\$ 763.00	✓
8	FRONT BUMPER UNDERRUN BAR	1	\$ 518.00	?
9	FRONT BUMPER CLOSING ELEMENT <i>Defhd</i>	1	\$ 173.00	✓
10	FRONT RADIATOR GRILLE <i>new at</i>	1	\$ 3,530.00	✓
11	QUATTRO EMBLEM <i>new</i>	1	\$ 106.00	+
12	FRONT RADIATOR STRIKER PLATE <i>new could</i>	1	\$ 244.00	✓
13	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 581.00	✓
14	FRONT BUMPER AIR GUIDE END CAP - RH <i>Defhd</i>	1	\$ 92.00	✓
15	FRONT BUMPER FOAM FILLER PIECE <i>Defhd</i>	1	\$ 177.00	✓
16	FRONT BUMPER CARRIER <i>Dented</i>	1	\$ 981.00	✓
17	FRONT BUMPER CARRIER BRACKET - RH	1	\$ 257.00	?
18	FRONT BUMPER CARRIER GUIDE SECTION - RH	1	\$ 39.00	?
19	FRONT BUMPER TOP COVER <i>Defhd</i>	1	\$ 129.00	✓
20	CAUTION STICKER <i>new</i>	1	\$ 14.00	✓
SUB TOTAL SPARE PARTS		:	\$ 9,759.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR CONDITIONER STICKER <i>Nec</i>	1 S	20.00 ✓	
22	HORN <i>Nec Nec</i>	1 S	195.00 ✗	
23	FRONT PARKING AID SENSOR - RH INNER	1	TBC ✗	
24	FRONT PARKING AID SENSOR - RH OUTER	1	TBC ✗	
25	FRONT PARKING AID SENSOR SEAL	4 S	14.00 ✗	
26	FRONT BUMPER WIRING SET	1 S	409.00 ✗	
27	FRONT FENDER - RH <i>Buckled</i>	1 S	1,427.00 ✓	
28	FRONT FENDER ATTACHEMENT PART <i>Abn</i>	1 S	66.00 ✗	
29	FRONT FENDER BRACE - RH <i>Best</i>	1 S	225.00 ✓	
30	FRONT FENDER BRACKET - RH	1 S	18.00	
31	FRONT FENDER TOP COVER - RH <i>neu</i>	1 S	31.00 ✗	
32	FRONT FENDER PANEL COVER - RH <i>neu</i>	1 S	40.00 ✗	
33	FRONT BONNET <i>Dented</i>	1 S	4,058.00 ✓	
34	FRONT BONNET ATTACHEMENT PART <i>Nec nec</i>	1 S	141.00 ✗	
35	FRONT BONNET IMPACT PROTECTION - LH / RH <i>Nec</i>	1 S	56.00 ✓	
36	FRONT BONNET STRIKER - RH	1 S	120.00 ✗	
37	FRONT BONNET LOCK	1 S	214.00 ✗	
38	FRONT BONNET BOWDEN CABLE	1 S	58.00 ✗	
39	FRONT BONNET RELEASE CABLE COVER	1 S	10.00 ✗	
40	FRONT BONNET RELEASE LEVER	1 S	14.00 ✗	
TOTAL SPARE PARTS		:	\$ 7,116.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	MOUNTING FOR HEADLIGHT - RH <i>checked</i>	1 S	118.00	✓
42	HEADLIGHT - RH <i>checked</i>	1 S	8,191.00	✓
43	HEADLIGHT POWER MODULE - RH	1 S	758.00	+
44	HEADLIGHT LED WITH HEAT SINK - RH	1 S	1,098.00	+
45	HEADLIGHT CONTROL UNIT	1 S	736.00	+
46	HEADLIGHT HOSE - RH	1 S	39.00	+
47	HEADLIGHT LIFT CYLINDER - RH	1 S	140.00	?
48	HEADLIGHT WASHER HOSE - RH <i>new</i>	1 S	125.00	+
49	FRONT WHEEL HOUSNG LINER - RH <i>new</i>	1 S	278.00	+
50	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	1 S	38.00	+
51	FRONT WHEEL SPOILRT <i>new</i>	1 S	155.00	✓
52	FRONT WHEEL COVER - LH / RH <i>new</i>	2 S	1,264.00	✓
53	S LINE EMBLEM <i>new</i>	1 S	128.00	✓
54	RADIATOR LOCK CARRIER <i>checked</i>	1 S	1,400.00	✓
55	RADIATOR LOWER BRACE - RH	1 S	57.00	?
56	RADIATOR BRACKET	1 S	16.00	?
57	INTER COOLER HOSE - RH <i>new</i>	1 S	315.00	+
58	COOLANT <i>new</i>	6 S	266.00	✓
59	FRONT RADIATOR AIR GUIDE - RH	1 S	58.00	?
60	FRONT RADIATOR AIR GUIDE - UPPER / LOWER	2 S	96.00	?
TOTAL SPARE PARTS		:	\$ 15,276.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLF 6888 S

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
61	FRONT RADIATOR AIR GUIDE - CENTER <i>NH u</i>	1	\$ 42.00	<i>x</i>
62	FRONT RADIATOR ASSEMBLY <i>NH u</i>	1	\$ 534.00	<i>x</i>
63	NOISE INSULATION <i>NH u</i>	1	\$ 915.00	<i>x</i>
<u>64</u>	FRONT NO PLATE <i>NH u NH u</i>	S/N	\$ 60.00	<i>x</i>
65	SUNDRIES <i>?</i>		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 34,102.00	
TOTAL LABOUR CHARGES		:	\$ 13,364.00	
GRAND TOTAL		:	\$ 47,466.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.