

YAP LEE MOTOR

NO 1 KAKI BUKIT AVENUE 6 #01-26
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6844 1555

TP Budget Direct.
Denise.

Vehicle No: SLX6054L

Date: 18/10/2021

Make/Model: Audi A4

0018 April

Chasis Number: WAUZZZF49JA121422

ESTIMATE COST OF REPAIRS

Qty	Descriptions List Item	Amount
1	Rear Bumper <i>Rehd.</i>	\$ 2,242.00 ✓
1	Rear Bumper Bracket RH <i>new</i>	\$ 22.00 +
1	Rear Bumper Retainer RH <i>Rehd</i>	\$ 89.00 ✓
1	Rear Bumper Reflector RH <i>new</i>	\$ 102.00 x
1	Rear Bumper Lower Garnish <i>new</i>	\$ 235.40 +
4	Reverse Sensor <i>new</i>	\$ 980.00 x
1	Tail Lamp RH <i>new</i>	\$ 976.80 +
1	Rear Fender RH <i>Dented.</i>	\$ 3,268.00 2644
1	Rear Door RH <i>Rehd</i>	\$ 2,786.00 +
1	Rear Door Lock RH	\$ 485.00 +
1	Rear Shock Absorber RH <i>new</i>	\$ 465.00 +
1	Rear Lower Arm RH	\$ 1,047.00 +
1	Rear Wheel Hub <i>new</i>	\$ 585.20 x
1	Rear Knuckle Arm RH <i>new</i>	\$ 1,324.00 x
1	Rear Quarter Glass RH	\$ 589.60 +
1	Rear Fender Innershield RH <i>new Rehd</i>	\$ 424.00 251
		\$ 15,621.00
Less 5%		\$ 781.05
		\$ 14,839.95

5226
4703.40

Special Nett Item

1	Rear Tyre <i>new</i>	\$	300.00	<i>x</i>
1	Rear Wheel Rim <i>cut</i>	\$	800.00	<i>600</i>
1	Rear Bumper Clip (1 Set) <i>new</i>	\$	60.00	<i>30</i>
1	Rear Fender Innershield Clip (1 Set) <i>new</i>	\$	60.00	<i>30</i>
1	Quarter Glass Sealant <i>new</i>	\$	60.00	<i>40</i>
		\$	1,280.00	

Labour cost

1	To do computerized Wheel Alignment	\$	200.00	<i>80</i>
2	To remove & refix undercarriage	\$	450.00	<i>x</i>
3	To remove & refix Reverse Sensor	\$	200.00	<i>60</i>
4	To remove & refix Quarter Glass RH	\$	180.00	<i>60</i>
5	To remove & refix inner trim for facilities repair	\$	180.00	<i>80</i>
6	To apply undercoating	\$	180.00	<i>80</i>
7	To panel beat	\$	1,000.00	<i>800</i>
8	To spray paint on affected areas	\$	1,000.00	<i>700</i>
		\$	3,390.00	

GRAND TOTAL

\$19,509.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5.81C

Adrian Lj
h/s 18/10/21
06 Days.

total: 726340
h/s: 5.81C