

Immediate Advice

To: AXA Insurance Pte Ltd 10/6/2022

Survey Details:

Date of loss	5-Aug-21]
Date of appointment	12-Oct-21]
Date of survey	13-Oct-21]
Location of survey	HUA MENG SPRAY PAINTING WORKSHOP	

Vehicle Details:

Claim Type:	Third Pa	Third Party Claim	
Vehicle number	GBL 135	5H	
Make and Model	TOYOTA	TOYOTA HIACE VAN TURBO 5DR M	
Date of registration	24/3/20	21	
Excess	-		
Market Value	\$	82,000.00	
Parf Rebate	\$	33,902.00	
Nett Loss	\$	48,098.00	

Repair details:

Initial Estimate	Ś	14,402.70
militar Estimate	۲ ا	= 1, 10=170

Proposed/Revised repair cost:

Parts	\$ 4,712.73
Check items (estimate)	\$ -
Labour	\$ 1,840.00
Total	\$ 6,552.73
Lump Sum(if applicable)	\$ 5,200.00

Number of days for repair	<u>5</u>



51 UBI AVE 1, #91-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Mandate:

Liability(TP)	%]
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	