

Келлет

TOTAL

N/S	O/S

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

*Not Authorised
C/L Rep & 5650/h
Penalty After Paying
7 days*

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: **Third Party**

Accident Date : 06.10.2021

Date: **09.10.2021**

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Nissan NV350" Reg. No. GBH4863J Claiming Against Your Insured Reg. No. SKJ180E			
1pc	Front Bumper <i>571.90</i>		<i>Buy 1cm</i> 595.00 N ✓
12pcs	Front Bumper Clips	3.50	<i>na</i> 42.00 N ✓
1pc	Front Bumper Corner Retainer LH		<i>CM</i> 152.00 N ✓
1pc	Front Bumper Fog Lamp LH <i>320.90</i>		<i>mg Bu</i> 339.00 N ✓
1pc	Front Bumper Fog Lamp Cover LH		<i>mg Di</i> 135.00 N ✓
1pc	Headlamp LH		<i>CM</i> 425.00 N ✓
1pc	Headlamp Lock Clip		<i>na</i> 12.50 N X
1pc	Front Door LH <i>1071.90</i>		<i>Buy/warp</i> 1,275.00 N ✓
1pc	Front Door Lower Hinge		<i>na</i> 110.00 N X
1pc	Front Door Lower Step Board		<i>CM</i> 150.00 N ✓
1pc	Front Door Weatherstrip		<i>na</i> 122.00 N X
1pc	Front Door Rubber Seal Lower		<i>na</i> 49.00 N X
10pcs	Front Door Trim Board Clips	5.50	<i>na</i> 55.00 N X
1pc	Front Wheel Cap LH		<i>na</i> 170.00 N ✓
1pc	Front Wheel Mudflap LH		<i>na</i> 102.00 N X
1pc	Front Upper Arm		<i>na</i> 345.00 N X
1pc	Front Lower Arm		<i>na</i> 230.00 N X
1pc	Sliding Door LH <i>1325.40</i>		<i>Buy/warp</i> 1,750.00 N ✓
10pcs	Sliding Door Trim Board Clips	5.50	<i>na</i> 55.00 N X
1pc	Sliding Door Inner Rear Reflective Sticker		<i>na</i> 45.00 N X
1pc	Rear Wheel Cap LH		<i>na</i> 165.00 N ✓
1pc	Rear Wheel Mudflap LH		<i>na</i> 130.00 N X
1pc	Rear Bumper <i>667.20</i>		<i>mg CM</i> 796.00 N ✓
10pcs	Rear Bumper Clips	3.50	<i>na</i> 35.00 N ✓
1pc	Taillamp LH <i>224.80</i>		<i>na</i> 435.00 N ✓
	Less 10%		7,719.50
			771.95
			6,947.55
			<i>255a</i>
1pc	Front Door Reg Label		<i>na</i> 45.00 SN /
1pc	Rear Wheel Bearing ??? Got two Rr Wheel Bearing		<i>na</i> 120.00 SN X
1pc	Front Wheel Bearing		<i>na</i> 245.00 SN X
1pc	Front Wheel Hub		<i>na</i> 596.10 SN X
1pc	Front Lower Arm Ball Joint		<i>na</i> 108.00 SN X
1pc	Front Knuckle Arm		<i>na</i> 385.00 SN X
1pc	Front Shock Absorber		<i>na</i> 145.00 SN X
1pc	Rear Shock Absorber		<i>na</i> 145.00 SN X
		C/F	8,736.65

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 09.10.2021

Accident Date : 06.10.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Nissan NV350" Reg. No. GBH4863J Claiming Against Your Insured Reg. No. SKJ180E		
		B/F	8,736.65 <i>201</i>
	To Conduct Electrical Check, Focus Headlamp		30.00
	To Dismantle / Transfer Door Fittings / Ancillary Accessories		<i>601</i> 150.00
	To Dismantle / Transfer Sliding Fittings / Ancillary Accessories		<i>601</i> 80.00
	To Dismantle / Replace Front Under Carriage to Facilitate Repair		<i>na</i> 140.00 X
	To Dismantle / Hi Pressure Press / Replace Front Wheel Bearing		<i>na</i> 90.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 <i>601</i>
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		<i>na</i> 110.00 X
	To Dismantle / Hi Pressure Press / Replace Rear Wheel Bearing		<i>na</i> 90.00 X
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00 <i>601</i>
	Labour Charge - Panel Beating, Repairing Of Front Corner Panel, Front Door Pillar, Step Panel, Door "B" Pillar, Rear Fender and Parts Replacement		900.00 <i>7001</i>
	To Respray Affected Areas (2k Pearl White)		1,400.00 <i>12001</i>
		Total :	<u>11,906.65</u>
			p

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: